

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONSERVATION DIV
S. 1st ST.
ARTESIA, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SNOW OIL & GAS, INC.

3. Address and Telephone No.

P.O. BOX 1277 ANDREWS, TEXAS 79714

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2030' FNL & 1980' FWL SECTION 25, T24S, R25E

5. Lease Designation and Serial No.

NM-81904

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

CAVERNS FEDERAL #1

9. API Well No.

30-015-22967

10. Field and Pool, or Exploratory Area

WILDCAT

11. County or Parish, State

EDDY COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU UNITED OIL SERVICES INC. NU BOP.
2. TIH 2-3/8" TBG. 3350', CIRC HOLE W/ 9.5 LB PER GALLON MUD LADEN FLUID.
3. SPOT 60 SACKS CEMENT, NEAT 3350' - 2750'. PULL TO 1950', SPOT 60 SACKS CEMENT WITH 2% CACL.
4. PULL TO CLEAR WOC 4 HRS. TAG TOC 1715'. POOH W/ TBG ND BOP.
5. SPOT 20 SACKS CEMENT, NEAT 50' TO SURFACE. CUT OFF WELLHEAD, CEMENT TO SURFACE BY VISUAL VERIFICATION. INSTALL DRYHOLE MARKER. RDMO.
6. CLEAN LOCATION.
7. CONTACTED JIM AMOS ON 10/12/95, FOR THE INTENT TO PLUG AND ABANDON.

Approved as to plugging of the well Bore
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Shannon J. Shaw

Title VICE PRESIDENT

Date 12/12/95

(This space for Federal or State office use)

Approved by Orig. Signed by Shannon J. Shaw

Title PETROLEUM ENGINEER

Conditions of approval, if any:

Date 1/22/96