	N M O O D CONT		C • 2 •
Porm [®] 9301 - May (10683)	UNT S. STATES PY DEPARTMEN, OF THE INTERIO GEOLOGICAL SURVEY	SUBMIT IN TRUELO	Form approved, Budget Bureau No. 42 R1424.
SUN official case this	DRY NOTLEE AND REPERD C	ick to a different reservair	NM 19246 G IF INDIAN, ALLOTTEE OR TRIBE NAME
+ 014. +	X NOV 1 3 1979		7. INT AGREEMENT NAME
Mesa Petroleu	n Co O. C. C.	······································	8. FARM OR LEASE NAME Nash Unit
B. ADDRESS OF OPERATOR		· · · · · · · · · · · · · · · · · · ·	9. WELL NO.
	uilding / Midland, Texas 79701	•••••	7
2. For Artics, of WELL, H See al. 6, space 17, hel At - arfage	teport location clearly and in accordance with any S ow.)	state requirements. [*]	10. FIELD AND FOOL, OR WILDCAT Und. Nash Draw-Morrow
Surface: 685	' FNL & 1295' FWL of Sec 18	r.	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA
Proposed Btm:	1315' FSL & 1320' FWL of Sec	2 7	Sec 18, T23S, R30E
4 HUEMER NO.	15. ELEVATIONS (Show whether DF,		12. COUNTY OF PARISH 13. STATE
	3012' GR		Eddy N. Mexico
16.	Check Appropriate Box To Indicate N	ature of Notice, Report, or C	5
	OTI E OF INTENTION TO :		TENT REPORT OF :
E.S. WATER SHUT:0	FP FUEL OR ALTER CASING	WATER SHUT OFF	REPAIRING WELL
OUNTER SHELTS	MUEDDER COMPLETE	FRACTURE TREATMENT	ALTERING CASING
7 TOOLOR AGAINZE	ABAN100N*	SHOOTING OR ACIDIZING	ABANDONMENT*
STRONG WELL	CHANGE PLANS	$(Other) = 9-5/8^{\circ}$ cas	
$s \Rightarrow t(2s) er(t)$		Completion or Recompl	of multiple completion on Well etlon Report and Log form.)
This report b	e contraction of the second state all pertinent well is directionally drilled, give subsurface location eing filed simultaneously with ocation may be on state land.		
181' west of a located appro state mineral 4673.71' (6471.10' (11,144.81' (3728'.	of 11,111' on 10-17-79'. Botto surface location (685' FNL & 13 ximately 380' FSL and 1115' FWL s. The 12-1/4" hole was logged 107 jts) 9-5/8" 47#, S95, LTC 151 jts) 9-5/8" 43.5#, S95, L 258 jts) set at 11,111' RKB wi s with casing on bottom - full	295' FWL Sec 18, T235 _ of Sec 7, T23S, R30 d, then 9-5/8" casing (btm) FC th collar at 11,050'	S, R3OE). Thus, BHL is DE, and is presently on g run on 10-20-79 as follows: and DV tool at 6511' and
0.3 D-19 + 0 by 400 sx cla while displac without succe Did not recove + 0.5 D-19 + mlass "H" (mi PM 10-21-79, not regain re 11 hours. Di	.22 R-5 + 1/4# celloflake (mixed ss "H" + 0.2 HR-5 (mixed at 19 ing. PD at 10:40 AM 10-21-79. ss. Closed hydril and reverse er any cement. Cement down 9-9 1/4# celloflakes (mixed at 12 xed at 15.7 ppg, yield 1.17/cu Opened DV tool at 3728'. Pum turns. Closed hydril and rever d not recover any cement. Atte the foregoing is true and correct	ed at 12.49 ppg, yiel 5.7 ppg, yield 1.17/c Opened DV tool at 6 circ down annulus ar 5/8" and thru DV tool .4 ppg, yield 1.97/cu . ft.) No returns wh bed 20 bbls mud throu rse circ down annulus empted to pump down S	d 1.94/cu. ft.) followed cu. ft.). Lost returns 5511' and attempted to circ ad up 9-5/8" csg for 7 hrs. at 6511' with 1350 sx LW u. ft.) followed by 200 sx nile cementing. PD at 11:30 ugh DV tool at 3728', but did s and up 9-5/8" casing for 9-5/8" casing, (cont.)
		ulatory Coordinator	DATE 11-7-79
(This space for Fed (Orig. 532.) G APPROVED BY	PEORGE H. TE #AT ACTING TITLE	DISTRICT ENGINEER	DATE NOV 0 8 1979
CONDITIONS OF A	PPROVAL, 1F ANY :		