

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

30-015-23031

5. Indicate Type of Lease

STATE ☐FEE ☐

6. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☐

GAS

WELL ☐

OTHER F/W Injection Well

2. Name of Operator

I &amp; W, Inc.

3. Address of Operator

P.O. Box 1685, Carlsbad, New Mexico 88220

4. Well Location

Unit Letter M : 1288' Feet From The S Line and 497' Feet From The W Line

Section 17

Township 22

Range 27

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3126

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1/10/00 (1.) Rigged up Dowell Cement Trucks. (2.) Flushed 27/8 casing with 10bbls. of fresh water. (3.) Pumped 25 sacks of cement with 2 % CaCl<sub>2</sub> slurry with yeild of 1.34. (4.) Shut well in with 125 PSI on 2 7/8 casing.
- 1/11/00 (1.) Ran 1" Tubing in hole tagged up at 450'. (2.) Spotted 6 sacks cement with 2% CaCl<sub>2</sub>. (3.) Shut well in over night.
- 1/12/00 (1.) Ran 1" tubing in hole, tagged up at 390'. (2.) Spotted 4 sacks class "C" neat cement @ 390'. (3.) Shut well in over night.
- 1/13/00 (1.) Ran 1" tubing in hole, tagged TOC at 320'. (2.) Pressure test 2 7/8 had 900 PSI, bled off to 600 PSI in 15 minutes. (3.) Spotted 6 sacks of cement @ 320' put 600 PSI on well. (4.) Shut well in over night.
- 1/14/00 (1.) checked well had 200 PSI on it. (2.) Ran 1" tubing in hole tagged up @315'. (3.) spotted 6 sacks of cement at 315'. (4.) Cement set for approx. 2 hours.

CONTINUED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Manager

DATE

2/1/2000

TYPE OR PRINT NAME

George Parchman

TELEPHONE NO.

885-6663

(This space for State Use)

APPROVED BY

TITLE

Field Rep I

DATE

8-10-00

CONDITIONS OF APPROVAL, IF ANY:

Post P&amp;R