

DATE	
TIME	
LOCATION	
WELL	
USGS	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P.O. BOX 2084
MIDLAND, TEXAS 79701
MAY 5 1981

Form C-103
Revised 10-1-

10. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR APPLICATIONS TO DRILL OR TO REOPEN OR TO REPAIR EXISTING RESERVOIR.
USE APPLICATION FOR PERMITS TO DRILL OR TO REOPEN OR TO REPAIR EXISTING RESERVOIR.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	2. Name of Operator Maddox Energy Corporation	3. Address of Operator Suite 900 Bland Building, Midland, Texas 79701	4. Unit Agreement No. UNIT LETTER <u>B</u> <u>2310</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>10</u> TOWNSHIP <u>24S</u> RANGE <u>28E</u>	7. Unit Agreement Name	8. Farm or Lease Name Aminoil Guitar	9. Well No.	11. Field and Name of Well Wildcat	12. County Eddy
13. Elevation (Show whether DT, RT, GR, etc.) 2991' GL								

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Plug back & test Bone Spring</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Change ownership + Lease Name</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See also well log in 6-11, and Plot 10523 Inland Sw. 75-22
MI & RU completion tools, circulate hole w/10# brine, remove wellhead and install BOP's. Pull tubing and packer. Run CL and set Bridge Plug on wire line at 11,350' and dump 35' cement on top. RD wire line. RU & run tubing. Spot 100' cement plug from 9514' to 9614'. Pull out of hole. WOC. TIH w/tubing to tag plug. Pick up 7600' and spot 100' cement plug from 7500' to 7600'. WOC. RU wire line. RIH to check plug and run CL and perforating log. Perf and treat Bone Spring and flow to clean up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Quindra B. Cary TITLE Operations Manager DATE 5/5/81
APPROVED BY W. O. Gressett TITLE Assistant Manager DATE MAY 06 1981