	- <u>N</u>	M.O.C.D. COPY		(* . 5	
Form 9–331 (Mag. 1962)	UNID ST	ALES SUBMIT IN TRIPLIC S		ed. au No. 42-R1424.	
(May 1963)		HE INTERIOR (Other instructions on re		5. LEASE DESIGNATOR AND BRIAL NO.	
	GEOLOGICAL SURVEY		NM-15295		
		6. IF INDIAN, ALLOTTE			
	this form for proposals to drill or to Use "APPLICATION FOR PERM			3 1980	
<u></u>			7. UNIT AGREEMENT N	AMP.	
OIL CAS		MAR 1 1 1980	ARTESIA.	OFFICE	
NAME OF OPERATO		U.S. GEULUGICAL SURVEY	8. FARM OR LEASE NAT	ME	
С &]	K Petroleum, Inc.	"CK" Feder	-a1		
ADDRESS OF OPER		9. WELL NO.			
P.O.	Drawer 3546, Midland,	2-v	2-Y		
	L (Report location clearly and in acco	10. FIELD AND POOL, OR WILDCAT			
	& 1781' FEL, Sec. 8, T-	Wildcat 11. sec., T., B., M., OR BLK. AND			
	, 1701 Fill, Bee. 0, 1	24 5, K-20-E, Eddy 60., MI	SURVEY OR AREA Sec. 8, T-24	4	
14. PERMIT NO.	15 ELEVATIONS	(Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISI	H 13. STATE	
TA ADIVITA NU.	3481.		Eddy	NM	
		• 9	Eddy		
6.	Check Appropriate Box	To Indicate Nature of Notice, Report, or	Other Data QUENT REPORT OF:		
				[]	
TEST WATER SH	UT-OFF PULL OR ALTER CA	SING WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TREAT	r MULTIPLE COMPLE	TE FRACTURE TREATMENT	ALTERING (ASING	
SHOOT OR ACIDI	ZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONME	INT*	
REPAIR WELL	CHANGE PLANS	(Other) (<i>off</i>	hole		
(Other)		Completion or Recom	ts of multiple completion pletion Report and Log fo	orm.)	
proposed work nent to this wo	c. If well is directionally drilled, give ork.)*	state all pertinent details, and give pertinent date e subsurface locations and measured and true verti	ical depths for all marke	rs and zones perti-	
casing. L collapsed	anded @ 1998'. Attempte . See attachment #1 fo	l" hole to 2000'. Ran 52 jts. ed to cement 8-5/8" casing and or detailed report. Well aband East and well will be drilled	casing rupture oned 3-10-80.	ed and	
	• •	→ 4	•		
		-			
8. I hereby certify	that the foregoing is true and correc	t			
SIGNED	C. Cara-	TITLE Administrative Supervis	or DATE 3-10)-80	
(This space for	Federal or State office use)				
	Orige og hij ander Her STATE	V COL IN CONTRACT OF SAL OF SAL OF	Stmme MP	(D. 1.1. man	
		TITLE TITLE	DATE	<u>R 1 1980</u>	
CONDITIONS (OF APPROVAL, IF ANY:				

•

÷

*See Instructions on Reverse Side

.

	VELL NAME	#2-Y CK Federal —	(Attachment #1) OPERATOR & K Petroleum, Inc.
		1650' FSL & 1781' FEL, Sec.	8, T-24-S, R-26-E, Eddy Co., NM.
	DATE	STATUS OF OPERATIONS	
$\left(\begin{array}{c} \\ \end{array} \right)$			
	3-7 -80	Survey; 12-1/2 hrs. Drlg. 1-1/2 hrs. TOOH; 4-1/2 hr ;3 hrs. WO wireline; Ran shoe and float collar, 5 3 cement baskets, 1 at 60 landed 8-5/8" casing at 1 pressure and no returns; feet, 54 bbls. shurfill c	e; 1-1/2° @ 2,000'; Mud wt. 8.4#; Vis 28; 1 hr. ; 1/2 hr. Circulate (pump in hole to clean hole); s. Run 8-5/8" casing; 1 hr. RU BJ Hughes and cement 52 jts. 2,003' 8-5/8", 24#, K-55, ST&C casing, with centralizers and with Halliburton DV tool @ 5,009',509 1', 1 @ 559', close DV tool, 1 at 478' above DV tool ,998', 2' off bottom; Circulated 20 minutes with 0 BJ Hughes cemented as follows:Pump 200 sks. 340 cubic ement, 1.52 cu. ft./sk. yield, with 1/4# celloflake 15 sks., 670 cu. ft., 120 bbls. 2% lodense cement,
(1.52 cu. ft./sk. yield, w sks. Class "C", 47 bbls. pressuring up with a tota casing ruptured and went mixed except 10 sks.; Put pressure, no circulating; casing @ 656' from surfac displacement was to be 12 to casing rupture; Total shoe of bottom of casing surface to 650' leaves 83 from 656' to 1,998'; At p BOP and TIH with 7-7/8" r attempt to get through ru	<pre>ith 1/4# celloflake/sk. and 10# gilsonite; Pump 200 1.32 cu. ft/sk. with 2% Ca Cl; Casing started 1 of 218 bbls. cement mixed and reached 2200 psi and on vacuum, still no returns; All of the above cement plug in casing and displaced with 124 bbls., 0 2 hrs. WO wireline truck; Tagged plug in 8-5/8" e; Total cement slurry pumped was 218 bbls., 4 bbls., 94 bbls. of cement out bottom of casing prior of 218 bbls. cement - 124 = 94 bbls. of cement out ; 124 bbls. displacement - 41 bbls. of cement from bbls. of cement or 1,342' of cement left in casing present ,preparing to NU casing at surface, install ill tooth bit, to commence drilling on cement and aptured casing;</pre>
	3-8 -80	pipe and NU; 2 hrs. TIH	ement; Mud wt. 8.4#; Vis 28; 8 hrs. Cut off conductor to drill cement left in casing; 11-1/2 hrs. Drill 2 hrs. Pull out to check bit, now back to drilling bit checked.
	3–9-80	hrs. Tripping to check b WO small bits and impres bit: 1 hr. POOH: 1 hr. T	ement and running on iron; Mud wt. 8.4#; Vis 28; 2 it; 1 hr. Drill cement; 1-1/2 hrs. TOOH; 10 hrs. sion block; 1-1/2 hrs. TIH; 3 hrs. Drlg. with 6-3/4" IH with impression block; 1-1/2 hrs Circulate wash down to metal; 2-1/2 hrs. Chain out with
	3-10-80	to drill through tight s LD DP & DC's; l hr. WO v Finding free point and c 3 hrs. LD casing, got 70	4#; Vis 28; 2 hrs. Tripping with bit #3; 3/4 hr. Try pot, jumped as though running on metal; 2-3/4 hrs. ireline to free point and cut off casing; 7-1/2 hrs. utting off casing; 3 hrs. LD casing, got 700' casing 0' casing; 6 hrs. RD, prep to skid over and re-drill; be changed on 3-11-80's report.
Ć		•	