## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MOT END MINTER BY		
	1	
DISTRIBUTION		
BANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OBCOOL	1	1

## OIL CONSERVATION DIVISION

Form	C - 1	03	
Revis	e d	10-	1 - 78

DISTRIBUTION	P. O. BO.	X 2088	Revised 19-1-78		
SANTA PE	SANTA FE, NEW MEXICO 87501				
FILE			ta. Indicate Type of Lause		
U.S.Q.S.	•		State X For		
LAND OFFICE			5. State Oil & Gas Lease No.		
OPERATOR		Ø <b>t</b>			
		RECEIVED -	L-4381		
SUNDRY	NOTICES AND REPORTS ON	H PROPOSALS.)			
1.		JUL 1 8 1980	7. Unit Agreement Name		
OIL X WELL X	OTHER-				
2. Name of Operator	01414	O. C. D.	B. Farm or Lease Name		
		ARTESIA, OFFICE	El Paso "B" State		
Ford Chapman & Associat	es •	ARTESIA, OFFICE	9. Well No.		
3. Address of Operator			1		
c/o Oil Reports & Gas S	c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240		10. Field and Pool, or Wrigeat		
4 1 ocation of Well	•	1			
A	330 FEET FROM THE North	LINE AND PEET FRE	ow Undes Sulphate Draw		
ORIT CETTER	•				
THE East LINE, SECTION	32 TOWNSHIP24	S PANGE 27E NMP			
mmmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
		Eddy			
<i>1:11111111111111111111111111111111111</i>	3351.4 GR				
16. Check A	ppropriate Box To Indicate N	Nature of Notice, Report or C	other Data		
NOTICE OF IN	TENTION TO:	SUBSEQUE	NT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING $[\overline{X}]$		
TEMPOPARILY ASANDON		CASING TEST AND CEMENT JOB			
PULL OR ALTER CABING	CHANGE PLANS	OTHER			
	$\Box$	DIREK			
CT HT F					
	(0)	toils and give nortinent dates includi	ng estimated date of starting any propose		
<ol> <li>Describe Proposed or Completed Operark) SEE RULE 1103.</li> </ol>	erations (Clearly state all perlinent det	ians, and give period in asies, inclusion			
•					

## Well plugged and abandoned 5/14/80 as follows:

Spotted 35 sacks cement on bottom Tagged top of plug at 2109 Spotted 35 sacks cement at 1900 Tagged top of plug at 1850 Spotted 35 sacks cement at 1250 Spotted 45 sacks across 10 3/4" Casing shoe at 210 Set 20 sack plug at surface with regulation marker. Mud between all plugs.

				1953 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
18.1 hereby certify that the information above is true and comple	te to the bost	t of my knowledge and belief.		
ALENED /k & ring // alles	TITLE	Agent	DATE	7/17/80
CONDITIONS OF APPROVAL, IF ANY:	TITLE	Reologist	DATE	10-10-64