

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 015 23287
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Malaga A
8. Well No.	2
9. Pool name or Wildcat	Undesignated

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Southwest Royalties, Inc.	
3. Address of Operator c/o Box 953, Midland, Texas 79702	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>24-S</u> Range <u>28-E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <u>Test Strawn zone</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged off Morrow zone from 12,246 - 12,394 setting CIBP 11,560 w/ 40' cement on top. (Well diagram and status when purchased from Phillips Petroleum Co. 9-1-90 attached). Perforated Strawn zone from 11,430 - 11,436 - Strawn zone uneconomical. Set permanent Model D packer w/ DR plug w/ 40' cement @ 11,191. To plug back to Bone Springs set 25 sx plug @ 11,050. Set 25 sx plug @ 9490. Base of 100' plug @ approximately 7090 - cut off casing approximately 7010'. Intend to perforate Bone Springs zone 6342' - 6373' as per C-103 filed 4-22-91.

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Agent DATE 5-16-91
TYPE OR PRINT NAME Ann E. Ritchie (915) TELEPHONE NO. 684-6381

(This space for State Use) ORIGINAL SIGNED BY Ann E. Ritchie

APPROVED BY State Engineer, DISTRICT II TITLE State Engineer DATE MAY 22 1991

CONDITIONS OF APPROVAL, IF ANY: