



LTR



Job separation sheet

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAY 16 '94

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Kaiser-Francis Oil Company

3. Address of Operator
P. O. Box 21468, Tulsa, OK 74121-1468

4. Well Location
Unit Letter F : 2310 Feet From The North Line and 1925 Feet From The West Line

Section 3 Township 24S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
301 GR 3018.6

WELL API NO.
30-015-23300

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Vasquez Com

8. Well No.

1

9. Pool name or Wildcat
Malage (Delaware)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cmt retainer @ 6055' & pumped 35 sxs cmt thru retainer. Dumped 2 sxs cmt on top.
2. Fill hole w/mud. Set a 25 sx cmt plug @ 2509'.
3. Cut off 9 5/8" casing & pulled 985' OOH & LD.
4. Pumped a 25 sx cmt plug @ 1220'.
5. Set 75 sx cmt plug 50' in and out of casing stub @ 1027'.
6. Set 75 sx cmt plug from 481'-380'.
7. Set 25 sx cmt plug from 30' to surface.
8. Cut off surface casing and installed dryhole marker.

P&A operations began: 3/31/94
P&A operations completed: 4/5/94

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Charlotte Van Valkenburg

TITLE

Technical Coordinator

DATE 5/12/94

TYPE OR PRINT NAME

Charlotte Van Valkenburg

918-491-4314

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY RAY SMITH

APPROVED BY


TITLE

OIL AND GAS INSPECTOR

DATE

MAY 15 1995

CONDITIONS OF APPROVAL, IF ANY:



LTR



Job separation sheet

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 14 1994

WELL API NO.	30-015-23300
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	-
7. Lease Name or Unit Agreement Name	Vasquez Com
8. Well No.	1
9. Pool name or Wildcat	Malage (Delaware)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	301 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Kaiser-Francis Oil Company
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468	4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1925</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>24S</u> Range <u>28E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 301 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following is our proposal to plug & abandon the above well:

1. Set cmt retainer @ 6075' & pump 35 sxs cmt. Sting out of retainer & dump 2 sxs cmt on top. Plug 2445' - 2612'
2. Cut off 9 5/8" casing & pull (est. 1200').
3. Set 75 sx cmt plug 50' in and out of casing stub.
4. Set 75 sx cmt plug from 480' - 380'.
5. Set 25 sx cmt plug from 30' to surface.
6. Cut off casing & install dryhole marker.

Estimated starting date: 2/15/94

Note: (6/93) CIBP set @ 11595' w/50' cmt on top. Set 50 sx cmt plug from 11150' - 11050'.
Set 50 sx cmt plug from 9450' - 9350'.
Delaware perms @ 6096' - 6181' o.a.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Jan Valkenburg TITLE Technical Coordinator DATE 1/12/94
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE 200 Rg DATE 2/9/94
CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAY 16 '94

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-23300
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Kaiser-Francis Oil Company		6. State Oil & Gas Lease No. -
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468		7. Lease Name or Unit Agreement Name Vasquez Com
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>1925</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>24S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>301 GR 3218.6</u>		9. Pool name or Wildcat Malage (Delaware)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cmt retainer @ 6055' & pumped 35 sxs cmt thru retainer. Dumped 2 sxs cmt on top.
2. Fill hole w/mud. Set a 25 sx cmt plug @ 2509'.
3. Cut off 9 5/8" casing & pulled 985' OOH & LD.
4. Pumped a 25 sx cmt plug @ 1220'.
5. Set 75 sx cmt plug 50' in and out of casing stub @ 1027'.
6. Set 75 sx cmt plug from 481'-380'.
7. Set 25 sx cmt plug from 30' to surface.
8. Cut off surface casing and installed dryhole marker.

P&A operations began: 3/31/94

P&A operations completed: 4/5/94

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlotte Van Valkenburg TITLE Technical Coordinator DATE 5/12/94
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY RAY SMITH

APPROVED BY Ray Smith TITLE OIL AND GAS INSPECTOR DATE MAY 15 1995

CONDITIONS OF APPROVAL, IF ANY: