

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY - 2 '90

WELL API NO.
30-015-23301

1. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 670, Hobbs, NM 88240

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 2 Township 22S Range 28E NMPM Eddy County

10. Elevation (Show whether OF, RKB, RT, GR, etc.)
3157' 6"

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU, PUMPED 250 BBLS DN CSG TO KILL WELL, TOH W/ 2 3/8" & 2 1/16" PROD TBG, TIH W/4" HOWCO CICR & 34 JTS 2 1/16" PH-6 HYDRIL TBG & 2 3/8" WS & SET CICR @ 9550 STING OUT CIRC WELL W/P&A MUD STING INTO CICR & SQZ WOLFCAMP PERFS 9834-55 W/55 SXS CLASS H CMT FINAL SQZ PRESSURE-3200 PSI CAP CICR W/5 SXS PULL UP HOLE & SET 235' BALANCED CMT PLUG F 8665 TO 8430 W/30 SXS CLASS C PULL UP HOLE & SET 225' BALANCED CMT PLUG F 7515 TO 7290 W/30 SXS CLASS C, TOH LD 2 1/16" IJ TBG & SETTING TOOL NDBOPE WELD ON 5 1/2" JT CSG & INSTALL CSG JACKS RIH W/FPI FREEPOINT 5 1/2" CSG @ 6998 JET CUT 5 1/2" CSG @ 6952, PULL & LD 5 1/2" CSG REC'D TTL 212 & 1 CUT JTS TIH W/ TBG TO 7002 CIRC WELLBORE W/P&A MUD SET 100' BALANCED CMT PLUG F 7002 TO 6902 W/30 SX CLASS C TAG PLUG @ 6910 SET 200' BALANCED CMT PLUG F 6300 TO 6100 W/ 30 SX CLASS C TOH W/1 JT PLUGGED TBG TIH TO 3800 & SET 200' BALANCED CMT PLUG FROM 3800 TO 3600 W/80 SX WOC 1 HR & TAG PLUG @ 3584 SET 200' BALANCED CMT PLUGS F 2700 TO 2500 W/52 SX & 550 TO 350 W/52 SX & 60' SURF PLUG F 60 TO GL W/16 SX CUT OFF WH INSTALL DRY HOLE MARKER, CHANGE STATUS TO PLUGGED & ABANDONED 4-28-90.

WORK STARTED 4-24-90 WORK ENDED 4-29-90

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 4/30/90 TITLE Staff Dir. Engr. DATE 4-30-90

TYPE OR PRINT NAME M. E. Akins TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY Johnny Robinson TITLE OIL AND GAS INSPECTOR DATE June 19, 1990

CONDITIONS OF APPROVAL, IF ANY:
OK
GW

10-10-10

RECEIVED

MAY 11 1910

U.S. DEPT. OF AGRICULTURE
BUREAU OF PLANT INDUSTRY