

7. METHODS OF HANDLING WASTE DISPOSAL:

- A. Drill cuttings will be disposed of in the drilling pit.
- B. Drilling fluid will be allowed to evaporate in the drilling pit until the pit is dry.
- C. Water produced during tests will be disposed of in the drilling pit. Oil produced during tests will be stored in test tanks until sold.
- D. Current laws and regulations pertaining to the disposal of human waste will be complied with.
- E. Trash, waste paper, garbage and junk will be buried in a separate trash pit and covered with a minimum of 24 inches of dirt. All waste material will be contained to prevent scattering by the wind. Location of the trash pit is shown on Attachment "C".
- F. All trash and debris will be buried or removed from the well site within 30 days after finishing drilling and/or completion operations.

8. ANCILLARY FACILITIES:

- A. None required.

9. WELL SITE LAYOUT:

- A. Attachment "C" shows the relative location and dimensions of the well pad, mud pits, reserve pit and trash pit, and the location of major rig components.
- B. This proposed well has been staked at an unorthodox location, as near to the floor of Robinia Draw as possible, in order to minimize necessary cut and fill. In addition, the rig layout has been rotated to V-door to the northwest to further reduce cut and fill. Average cut and fill should be about 4 feet with a maximum cut of less than 10 feet.
- C. The pad and pit area has been staked and flagged.

10. PLANS FOR RESTORATION OF THE SURFACE:

- A. After completion of drilling and/or completion operations, all equipment and other material not needed for operations will be