

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-015-23441

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
Bird Com

8. Well No.  
1

9. Pool name or Wildcat  
Cass Draw Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
Chi Operating, Inc.

3. Address of Operator  
P.O. Box 1799; Midland, TX 79702

4. Well Location  
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 12 Township 23S Range 27E NMPM Eddy County  
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐  
OTHER: ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g., pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-04-97 - MIRU. Lined pit and started flowing well down.  
11-05-97 - Notified Tim Gunn w/ OCD. Pumped brine down tbq; Circ. hole w/ mud.  
11-06-97 - Contacted Tim Gunn. POOH w/ tbq. RIH w/ gauge ring, stacked out @1150', 5000' and 9845'. POOH w/ wireline. Ken Livingston on location.  
11-07-97 - Contacted Tim Gunn. RIH w/ 7" CIBP, set @ 9845' and tagged. RIH w/ dump bailer; dumped 6 sx C cmt 9845-9810'. Cut 7" csg @ 7404'.  
11-11-97 - Started out of hole w/ 7" csg.  
11-12-97 - Contacted Ken Livingston w/ OCD. Finished POOH w/ 7" csg. Circulated hole and pumped 60 sx C cmt @ 7454'.  
11-13-97 - Ken Livingston on location. Tagged plug @ 7250'. Circulated hole and pumped 50 sx C cmt 5914-5756'. Circulated hole and pumped 65 sx C cmt 3561-3361'. Tagged plug @ 3375'. Circulated hole and pumped 60 sx C cmt 1017-835'. Loaded hole and pumped 65 sx C cmt 477-279'. Contacted Gary Williams w/ OCD.  
11-14-97 - Tagged plug @ 284'. Pumped 10 sx C cmt 30'-surface. RDMO.  
11-19-97 - Cut off wellhead, installed dry hole marker. Leveled cellar, backdragged location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer DATE 11/ 18/ 97  
TYPE OR PRINT NAME James F. Newman, P.E. TELEPHONE NO. 915-687-1994

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 9/18/98  
CONDITIONS OF APPROVAL, IF ANY: