				~		CI	
		State of New Mex	ico			Form C-101	
Submit to Appropriate	Energy, Minerals and Natural Resources Department					Revised 1-1-89	
State Lease - 6 copies Fee Lease - 5 copies OIL CONSERVATION DIVISION					API NO. (assigned by OCD on New Wells)		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 Santa Fe, New Mexico 87504-2088					30-015-2348900 5. Indicate Type of Lease		
DISTRICT II B.O. Drawer DD. Artesia, NM 88210					5. Indicate Type of Lease STATE FEE K 6. State Oil & Gas Lease No.		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410							
	ON FOR PERMIT TO	D DRILL, DEEPEN, O	R PLUG BACK				
1a. Type of Work:			JESIA, OFFICE	7. Lease Nar	ne or Unit Agre	ement Name	
DRILL	RE-ENTER	DEEPEN	PLUG BACK				
b. Type of Well: OIL OAS WELL WELL X OTHER SINCLE ZONE X ZONE					Cochell Com		
2. Name of Operator					8. Well No.		
Quinoco Petroleum, Inc./					9. Pool name or Wildcat		
3. Address of Operator D. O. Box 3781	11, Denver, Co	orado 80237	×		ng, <u>Morr</u> a	W Alta	
4. Well Location	: 1980 Feet Fr		Line and	990 Feet	From The	East Line	
Unit Letter	:198010011				Eddy	County	
Section 30) Townst	ip 23S Rar	_{ige} 28E	NMPM	Eddy ///////////////////////////////////		
<i>\</i>		10. Proposed Depth	1	11. Formation		12. Rotary or C.T.	
		<u>+</u> 12,150'		Atoka			
13. Elevations (Show whether 3,119' KB	DF, RT, GR, etc.)	4. Kind & Status Plug. Bond	15. Drilling Contra	ictor	16. Approx. D 11/15,	ate Work will start /89	
	/DI/DD	OPOSED/CASING AN	ND CEMENT PRO	OGRAM			
LAISTING	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPT	H SACKS O	F CEMENT	EST. TOP	
SIZE OF HOLE	16"	65#	454'	850		Surf	
14-3/4"	10-3/4"	40.5#	7400'	<u> </u>			
9-7/8"	7-5/8"	29.7# & 33.7#	9680'				
12,424-27' follows:	& 12,490-94') a	to abandon the nd recomplete th ll well if neces	e cocherr com	1 00 0.00			
NU BOP'	S.	und seal assembly					
2. POOH w/	2-3/0 cubing a	1 5" CIBP @ <u>+</u> 12,	150' and dump	50' of cm	t on top	of plug.	
			,	ADDOCHIC I		700 _ DATS	
4. Pert squeeze notes 11,000 kp.				PERMIT PAR UNLESS DAT	. 4	> - (-90)	
Please see	reverse side.						
ZONE, GIVE BLOWOUT PREY	ENTER FROOKAN, a Tatt	GRAM: IF PROPOSAL IS TO DEEL					
I hereby certify that the infor	mation above is true and comp	de to the best of my knowledge a	Production	n Technicia	n Di	ATE 11/7/89	
SIONATURE	ly S. Dec.	hardson 1			TE	ILEPHONE NO.	
TYPE OR PRINT NAME							
(This space for State Use)	ORIGINAL S MIKE WILLA	AMS -				DEC - 7 1989	
AND CUTTO BY	SUPERVISO	R. DISTRICT IS	TALE		D	A1B	
CONDITIONS OF APPROVAL	, IF ANY:						

_

- 5. TIH w/pkr and set $0 \pm 11,400'$.
- 6. Squeeze w/75 sx class HW/retarder for 3 to 4 hrs pump time, WOC.
- 7. TOOH, PU bit & scaper, drill out cmt.
- 8. Press test to 1000#.
- 9. Circ hole clean with a clean packer fluid prior to RIH w/tbg conveyed guns. On 2-3/8" tubing run tubing conveyed guns spaced out w/a Guiberson Uni-packer VI into hole and set the packer at <u>+</u> 10,500'. Hydrotest tbg while running in hole. ND BOP's and NU wellhead.
- 10. Swab hole down to + 8,000'. Drop bar and perforate Atoka from 11,524' to 11,530' with 2 jspf large diameter 0.50" holes. (12 shots total).
- 11. Flow test and evaluate well.

Evaluate for additional stimulation with recommendations to follow.