

COPIES RECEIVED	3
DISTRIBUTION	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED
DEC 10 1981

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. D.
ARTESIA, CHIEF

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator HNG OIL COMPANY	8. Farm or Lease Name Pardue 33 Com.
3. Address of Operator P. O. Box 2267, Midland, Tx 79702	9. Well No. 1
4. Location of Well UNIT LETTER 0, 1980 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 33 TOWNSHIP 23S RANGE 28E NMPM.	10. Field and Pool, or Wildcat Und. Culebra Bluff Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3062.4' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER PB to Bone Springs from Morrow <input type="checkbox"/>

SUBSEQUENT REPORT OF: 10/13/81

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set a blanking plug in Baker F-1 packer at 12,360'. Spot 1/2 bbl cement on top of packer. * Minimum 35' of cement

Pull tubing to 10,700' and spot 35 sacks Class H across liner top.

Perforate the Bone Springs (47 holes .39") as follows:

6244	6360	6454	6520	6742	6824
6252	6372	6460	6540	6756	6840
6270	6378	6466	6562	6764	6851
6282	6388	6472	6600	6770	6856
6290	6410	6484	6608	6778	6861
6320	6420	6490	6626	6790	6867
6325	6430	6502	6724	6800	6884
6335	6438	6508	6734	6812	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Betty Gildon TITLE Regulatory Analyst DATE 12/8/81

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE DEC 11 1981

CONDITIONS OF APPROVAL, IF ANY: * As Noted Above