. C COPIES RECEIVED	
P STRIBUTION RECEIVED	Form C-103 Supersedes Old
NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
F.LE 0.0T 1 / 1001	
U.S.G.S. OCT 1 4 1981	Sa. Indicate Type of Lease
OPERATOR OFFICE	State     Fee     X       5, State OII & Gas Lease No.     Image: State No.
ARTESIA, OFFICE	
SUNDRY NOTICES AND REPORTS ON WELLS	700000000000000000000000000000000000000
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
HNG OIL COMPANY /	Pardue 33 Com.
3. Address of Operator P. O. Box 2267, Midland, Texas 79702	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER 0 1980 FEET FROM THE East LINE AND 660 FEET FROM	Und Morrow
THE South Line, section 33 TOWNSHIP 235 RANGE 28E NMPM.	<i>CHIIIIIIIIIIII</i>
15. Elevation (Show whether DF, RT, GR, etc.)	12, County
3062.4' GR	Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report or Otl	per Data
	REPORT OF: 8/31/81
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
OTHER Recompletion i	n Morrow Formation
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	
work) SEE RULE 1703.	estimated date of starting any proposed
	estimated date of starting any proposed
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'	estimated date of starting any proposed
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'	
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn	
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.	
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn	
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20).</pre>	to 1100 psi. OK.
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.	to 1100 psi. OK.
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w</pre>	to 1100 psi. OK.
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry</pre>	to 1100 psi. OK.
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.</pre>	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500</pre>	to 1100 psi. OK. between runs. 7/20 sx. C1 H mixed gals 7.5% Morflo BC
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.</pre>	to 1100 psi. OK. between runs. 7/20 sx. C1 H mixed gals 7.5% Morflo BC
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6</pre>	to 1100 psi. OK. between runs. 7/20 sx. C1 H mixed gals 7.5% Morflo BC
<ul> <li>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'</li> <li>9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.</li> <li>9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20).</li> <li>9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry</li> <li>9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.</li> <li>10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls.</li> </ul>	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6</pre>	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
<ul> <li>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'</li> <li>9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.</li> <li>9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20).</li> <li>9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry</li> <li>9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.</li> <li>10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls.</li> </ul>	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'          9/1/81 - Tested upper Strawn squeeze to 1100 psi. 0K. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.         9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20).         9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry         9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.         10/1/81 - Perforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls.	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
<pre>Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. 0K. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bb1. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bb1s. (OVEN </pre>	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls. (OVER 18. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. stere	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280'          9/1/81 - Tested upper Strawn squeeze to 1100 psi. 0K. and lower Strawn Tested Atoka squeeze to 1000 psi. ok.         9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20).         9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry         9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg.         10/1/81 - Perforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls.         (OVER	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.
Cement retainer set at 11,282' on 8/26/81 was tagged at 11,280' 9/1/81 - Tested upper Strawn squeeze to 1100 psi. OK. and lower Strawn Tested Atoka squeeze to 1000 psi. ok. 9/15/81 - Perforated Morrow 12,920' - 12,929' (.25" 20). 9/18/81 - Swabbing FL 400' start 8500' no show of gas, 400' fluid entry 9/27/81 - MIRU well service unit, set bridge plug at 12,770' cemented w at 16 ppg. 10/1/81 - Peforated Morrow 12,478' - 12,605' (.32" 10). Acidized w/500 followed w/2000 gals w/500 SCF N2 bbl. Opened to pit on 32/6 RU Swab, FL at 1000', total recovered 70 bbls. (OVER 15. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. stewers	to 1100 psi. OK. between runs. 7/20 sx. Cl H mixed gals 7.5% Morflo BC 4" chk, well died.

10/3/81 - SITP 1800 psi., blew down in 30 min, swab 7 hours w/FL 3800' - 9000'; show of gas w/swab runs, rec. 62 BW.

; ;

10/5/81 - 7 hours swab w/FL ()-8500'; rec. 14 BF, slight show of gas. Released swab unit; DFR pending furhter activity.

4