

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 13 1981

O. C. D.

ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator AMINOIL USA, INC. / 3. Address of Operator P.O. Box 10525; Midland, Texas 79702 4. Location of Well UNIT LETTER K 1980 FEET FROM THE south LINE AND 1980 FEET FROM THE west LINE, SECTION 14 TOWNSHIP 24-S RANGE 28-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 2978.5 GL	7. Unit Agreement Name Willow Lake Unit 8. Farm or Lease Name Willow Lake Unit 9. Well No. 4 10. Field and Pool, or Wildcat Malaga Morrow 12. County Eddy
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in and rig up Pulling Unit. Trip in hole w/ tbg 1200' and load hole w/ 9.5#/gal. fluid. Rig up cementer and spot cmt plugs as follows:

Plug #1 - 130 sx class "H" w/ 2% CaCl₂ from 1200' - 1100'
Plug #2 - 140 sx class "H" w/ 2% CaCl₂ from 450' - 350' & tag
Plug #3 - 75 sx class "H" w/ 2% CaCl₂ from 50' - surface

Rig down cementer and Pulling Unit. Cut off casing head 4' below GL, weld on plate and P&A marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE District Operations Mgr. DATE October 9, 1981

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE OCT 13 1981

CONDITIONS OF APPROVAL, IF ANY: