		4 4	
NO. OF COPIES RECEIVED] .	and the second	Form C-103
DISTRIBUTION	1 · · ·	RECENCE BY	Supersedee Old C=102 and C=103
SANTA FE	NEW MEXICO OIL CON	ERVATION COMMISSION	Effective 14-68
FILE		MAR 12 1984	Sq. Indicate Type of Lease
U.8.G.8.			State X Fee
LAND OFFICE		• Q. C. D. •	5, Btate Oil 6 Gas Lease No.
OPERATOR]	ARTESIA, OFFICE	V-144
DO NOT USE THIS FORM FOR PA	RY NOTICES AND REPORTS ON OPERALE TO DRILL OR TO DESPENDENT OF PLUE PLUE PLUE PLUE PLUE PLUE PLUE PLUE	ACK TO A DIPPERENT RESERVOIR. Ch proposals.)	7, Unit Agreement Name
1. OIL BAB WELL X	STNER.		8. Form or Lease Name
2. Name of Operator W.A. Moncrief, Jr.			Crooked Creek State Com
3. Address of Operator		<u> </u>	9. Well No.
400 Metro Gldg., Midla	and, Texas 79701		1
4. Location of Well			10, Field and Pool, or Wildcat
UNIT LETTERK	1980 PEET PROM THE SOUTH	LINE AND PEET P	Mosley Canyon
	1 24.6	24E	
THE West LINE, SECTI	1		~~ <i>[[]]]]]]]</i>]]]]]]]]]]]]]]]]
	15. Elevation (Show whethe	DF, RT, GR, etc.)	12. County
	3993 GD.	4010 КВ	Eddy
18. Check	Appropriate Box To Indicate	Nature of Notice, Report or	Other Data
NOTICE OF I	NTENTION TO:	SUBSEQUE	INT REPORT OF:
	PLUE AND ABANDON	AEMEDIAL WORK	
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPHS.	PLUE AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	•	OTHER	······································
other	C	0THER	
OTHER	Clearly state all pertinent de		ing estimated date of starting any proposed
		tails, and give pertinent dates, includ	ing estimated date of starting any proposed
(1.) The production	n from Canyon perfs 8972	tails, and give pertinent dates, includ	
(1.) The production proposes to plug and	n from Canyon perfs 8972 abandon.	tails, and give pertinent dates, includ -8987' has declined to	zero and operator
(1.) The production proposes to plug and (2.) Top of comment	n from Canyon perfs 8972 abandon. is at 7670' outside cas	ails, and give pertinent dates, includ -8987' has declined to ing by temperature surv	zero and operator vey.
(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as	adds, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone	zero and operator vey.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on:	zero and operator vey.
(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'.	zero and operator vey. conservation
(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'.	zero and operator vey. conservation
(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'. plug in and out of 4½"	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'.	zero and operator vey.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan. 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack Operato 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'.	zero and operator vey. conservation
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack Operato (D.) 25 sack 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or	zero and operator vey. conservation wherever casing is cut.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack Operato (D.) 25 sack 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or	zero and operator vey. conservation wherever casing is cut.
(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 4490'. plug at 2775' (in and c	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± on but of 8-5/8" casing sho	zero and operator vey. conservation wherever casing is cut. De). Operator will tag
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (Derato (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± on but of 8-5/8" casing sho	zero and operator vey. conservation wherever casing is cut. De). Operator will tag
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (Y.) 10 sack</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (Y.) 10 sack</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CÍBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (Y.) 10 sack</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (D.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (Y.) 10 sack</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 430' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± on out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou ug.	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± on out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan. 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan 18. I hereby certify that the information 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 430' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, inclus -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De).
<pre>(1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (E.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan</pre>	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug at 8210'. plug in and out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 430' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, includ -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De). olug from all partners.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan. 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan 18. I hereby certify that the information 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug at 8210'. plug at 8210'. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 2775' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, inclus -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De). olug from all partners.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan. 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan 18. I hereby certify that the information 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug at 8210'. plug at 8210'. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 2775' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, inclus -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De). olug from all partners.
 (1.) The production proposes to plug and (2.) Top of cement (3.) Operator plan. 3-9-84 between Mike W (A.) 25 sack (B.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (C.) 25 sack (F.) 35 sack this pl (G.) 25 sack (H.) 10 sack (4.) Operator plan 18. I hereby certify that the information 	n from Canyon perfs 8972 abandon. is at 7670' outside cas s to plug as follows as illiams and Dewey Thornt plug on top of CIBP at plug at 8210'. plug at 8210'. plug at add out of 4½" r will tag this plug. plug at 5,000'. plug at 5,000'. plug at 4490'. plug at 2775' (in and ou plug at 430' (in and ou plug at the surface. s to P&A as soon as he r	tails, and give pertinent dates, inclus -8987' has declined to ing by temperature surv duscussed by telephone on: 9039'. casing cut at 7600'± or out of 8-5/8" casing sho at of 13-3/8" casing sho receives permission to p	zero and operator vey. conservation c wherever casing is cut. De). Operator will tag De). Delug from all partners. <u>3-9-84</u> <u>DATE</u> <u>3-9-84</u>