

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. --
7. Unit Agreement Name --
8. Farm or Lease Name Nymeyer
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated North Loving Morrow
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-

Name of Operator
Coquina Oil Corporation /
Address of Operator
P. O. Drawer 2960, Midland, Texas 79702
Location of Well

UNIT LETTER F 1980 FEET FROM THE West LINE AND 2310 FEET FROM
THE North LINE, SECTION 15 TOWNSHIP 23S RANGE 28E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3001' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REEL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run 66 jts 7-5/8" 39# P-110 F1-4S Casing 2415'

Top of Liner @ 9512' Bottom of Liner @ 11,942'

Cmt w/555 sx Class H w/1% CFR-2. WOC 18 hours. Tag cmt @ 9387'. Drill 125' cmt to top of liner. Test liner top to 2000 psi for 15 min. o.k. Drill cmt 55' and float collar. Press to 2000 psi for 30 min. o.k. Displace hole w/brine and drill shoe. Now drlg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Billy M. Pribe TITLE Drilling Manager DATE June 17, 1981

APPROVED BY M. Williams TITLE OIL AND GAS INSPECTOR DATE JUN 19 1981

CONDITIONS OF APPROVAL, IF ANY: