

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUN 16 1981

L. S. O.  
LAND OFFICE

1. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. State Oil & Gas Lease No. L-5386
7. Unit Agreement Name
8. Farm or Lease Name State DR
9. Well No. 1
10. Field and Pool, or Wildcat Und. Herradura Bend Del.
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - M" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: <u>Dry Hole</u>
2. Name of Operator CITIES SERVICE COMPANY
3. Address of Operator P. O. Box 1919 Midland, Texas 79702
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>22S</u> RANGE <u>27E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3074.9' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T. D. 2605' Sand. Shut-in waiting approval to plug and abandon. Drilled a 8" hole from 350' to a T.D. of 2605' in sand. Bailed from the Ramsey Sand, O BO: + 214 BW, 12 hrs. It is proposed to plug and abandon this well in the following manner:

1. MIRU pulling unit and spot a 35 sack cement plug @ approx. 2605'-2505'
2. POOH and lay down tbg to 2375' and spot a 35 sack cement @ approx. 2375'-2275' across top of Delaware Ls. @ 2328'.
3. POOH and lay down tbg to 1286' and spot a 35 sack cement plug @ approx. 1286'-1186', across top of Salt @ 1236'. \* + T<sub>g</sub>
4. POOH and lay down tbg to 400' and spot a 35 sack cement @ approx. 400-300', half in and half out of 8-5/8" casing shoe @ 349' \* + T<sub>g</sub>
5. Lay down remaining tbg and dump a 10 sack cement Surface plug in top of 8-5/8" casing @ approx. 30-0' G.L.
6. Install 4" Dry hole marker, RD Pulling Unit and Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. Spaulder TITLE Reg. Oper. Mgr.-Prod. DATE June 25, 1981

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE JUL 01 1981

CONDITIONS OF APPROVAL, IF ANY: \* As Noted Above

Notify N.M.O.C.C. in sufficient time to witness  
Plugging