

Memo

From
Larry Brooks
Geologist

To 4/30/85

RIH w/ cmt, retainer, latch
broke, had to mill retainer &
Baker model D type packer.
Drilled bp rthr and pkr. RIH w/
RTTS @ 11362 & SQZ off Morrow perfs.

B