

=====

WELL: PARDUE FARMS "27" #2 (W/O)
PROJECT: PPDC - 82.167968%

STATE: NM
COUNTY: EDDY

PBTD: 6,246

=====

11/04/91

FIRST REPORT: WORKOVER OBJECTIVE; PLUGBACK FROM BONE SPRINGS & COMPLETE BRUSHY CANYON. MIRU Clarke WS. Unseat pmp, hot wtr dwn tbg w/35 BPW & dwn csg w/45 BPW. POOH w/ rds & pmp. Released TAC & tag'd PBTD @ 7300'. Strapped OOH w/ tbg. RU Black Warrior, RIH w/4-1/2" gauge ring to 6300', Ok. PU RIH w/ CIBP & set @ 6242'. Tst to 1500 psi, Ok. Ran CBL f/6242' to 4242', good bond. Perf Brushy Canyon @ 6045', 48', 53', 56', 73', 77', 82'; 6151', 71', 75', 79', 6209', 33', 36, 40' (15' Holes @ 1 JSPF, .5" entry using 13 gr charges) w/3-1/8" HSC guns. SDFN. DC: \$5,500 CTD: \$5,500

11/05/91

RIH w/ tbg open-ended to 6240'. Circ hole clean & spot 1500 gals 15% acid over Brushy Canyon perfs 6045'-6240'. POOH w/ tbg. Frac same perfs dwn 4-1/2" csg as follows: 4000 gal 40# gelled wtr pre-pad w/330 gals SI-102 SI @ 25 BPM & 1500 psi. 22,000 gals 40# GWX-9 pad @ 30 BPM & 1500 psi. 5500 gals 40# GWX-9 w/2.0 ppg 20-40 @ 30 BPM & 3000 psi. 6500 gals 30# GWX-9 w/4.0 ppg 20-40 @ 30 BPM & 3000 psi. 7500 gals 30# GWX-9 w/6.0 ppg 20-40 @ 34 BPM & 1500 psi. 8500 gals 30# BWX-9 w/8.0 ppg 20-40 @ 43 BPM & 1000 psi. 2200 gals 2% KCL flush to btm perf @ 43 BPM & 800 psi. Max press 3000 psi, avg pressure 1500 psi. 54,000 gals GWX-9 & 151,380 20-40 total. ISIP 180 psi. 15 min 120 psi. TLTR 1417 bbls. SDFN. DC: \$27,500 CTD: \$33,000

11/06/91

Csg on vac. RIH w/ pkr, SN & tbg. Tag'd 52' sd, PU & set pkr @ 6000'. RU to swb, swb'd 7 hrs recovering 56 BLW (initial FL 4200' f/surface, final @ SN) & started blowing some gas. Rel. pkr & POOH. SDFN.

11/07/91

PU & GIH w/ Bulldog bailer. C.O. sd f/6178' to 6242' PBTD. Had 64' of sd fill. POOH & LD bailer. Perfs f/6045' to 6240'. RIH w/2-1/2" slotted BPMA, SN, 8 jts 2-3/8" tbg, TAC, 189 jts 2-3/8" tbg. Lnd btm @ 6126'. SN @ 6096'. TAC set @ 5839'. PU & GIH w/2" X 1-1/4" X 16' RHTC pmp,