	(HALLIBURTON MIDLAND	÷4	I	561
(, Dinero Operating	LABORATORY WA	ATER ANALYSIS	No. <u>W83-613</u> July 19	
Dinero Plaza A Drawer 10505 Midland, Tx79	ttn: Mr. L. C. Mc Clure	This report is the prope it nor any part thereof or disclased without fir of laboratory managen course of regular busin and employees thereof Company.	erty of Holliburton Com nor a copy thereof it st securing the express ment; it may however,	npany and neither to be published written approval be used in the
Submitted by <u>Floyd D</u> Well No. <u>Giovengo #1</u> County	(Bone Spring	z Area)	Brushy Canyo	$\boldsymbol{\zeta}$
Resistivity				
Specific Gravity	<u>1.184 @ 60°</u> _	RECE	IVED BY	
рН			17 1983	
Calcium (Ca)	19,100		<u>C D.</u>	*MPL
Magnesium (Mg)		ARTES	IA, OFFICE	
chlorides (Cl)			<u> </u>	
Sulfates (SO ₄)			<u> </u>	
Bicarbonates (HCO ₃)			<u></u>	<u>\</u> _
Soluble Iron (Fe)			<u> </u>	
API Oil Gravity:	40 @ 60°	······		
Remarks:	· · · · · · · · · · · · · · · · · · ·		*Milligroms	per liter
	Respectfully	submitted,		
Analyst Wright	HALLIBURTON COMPANY			

Floyd Dill

MPANY **T**/ By. 0 DIVISION CHEMIST

NOTICE

This report is limited to the described sample tested. Any user of this report agrees that Halliburton shall not be liable for any loss or damage, whether it be to act or amission, resulting from such report or its use.