

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 22 '90

WELL API NO.
30-015-23757

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Texaco Producing Inc. /

3. Address of Operator
P. O. Box 730 Hobbs, NM 88240

4. Well Location

7. Lease Name or Unit Agreement Name
Malaga Harroun 6 Com

8. Well No.
1

9. Pool name or Wildcat
Malaga Atoka

Unit Letter F : 1980 Feet From The North Line and 1830 Feet From The West Line

Section 6 Township 24S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
2954' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Load tbg. Set plug. Attempted to release pkr.
2. Ran free pt. Cut off 2-3/8" tbg @ 11,700'.
3. Ran in hole w/ overshot & jars. Jarred on packer, failed to release packer.
4. GIH w/ wash pipe. Tagged fish @ 11,700'. Ran shoe to 11,840' drilled on/off tool. Circulated clean. POH.
5. TIH w/ overshot, bumper sub and jars. Cut fish off 11,743. Received 48'.
6. Ran in hole w/cut rite shoe. Drilled on pkr from 11,845' to 11,847'.
7. TIH w/ 5-5/8" outside cutter. Cut fish off @ 11,811. Received 57' tbg.
8. TIH w/ overshot, Caught fish @ 11,811, worked loose. Received all of pkr. (Cont. on attachment.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Ridenour TITLE Engineer's Assistant DATE 8-21-90

TYPE OR PRINT NAME L. D. Ridenour TELEPHONE NO. 393-7191

(This space for State Use)
ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR DISTRICT II
APPROVED BY _____ TITLE _____ DATE AUG 23 1990

CONDITIONS OF APPROVAL, IF ANY: