

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISS'N
SUBMIT IN TRIPPLIC.
Draw on both instructions on
reverse side
Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 27919

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DEWEY

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

(Bone Spring) Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 24, T-24-S, R-28-E

12. COUNTY OR PARISH 13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DINERO OPERATING COMPANY ✓

3. ADDRESS OF OPERATOR

P.O. DRAWER 10505, MIDLAND, TEXAS 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 560' FWL

Sec. 24, T-24-S, R-28-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON* Temp. X

REPAIR WELL

CHANGE PLANS

(Other)

Plug Back X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Temporarily abandon the Bone Springs formation by setting a C.I.B.P.

at 6300 ft. and put 2 sacks of cement on top of plug.

Test casing to 2500 lbs.

Perforate 4½ 10.5 lbs. casing as follows.


4238 to 40 2 shots per foot

4244 to 49

4251 to 57

4260 to 80

Acidize with 2000 gallons acid to evaluate.



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

Posted ID 2
7-23-82
Zow pff

18. I hereby certify that the foregoing is true and correct

SIGNED

Lavonda Norman

TITLE

Production Supervisor

DATE

July 14, 1982

(This space for Federal or State office use)

APPROVED BY

(Orig. Seal) PETER W. GILHAM

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 20 1982

FOR

JAMES A. GILHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side