• • • • • • • • • • • • • • • • • • •	Form approved.	.1
Form 3160-5 SUBMIT IN TRU ATE.	Budget Bureau No. 1004–0135 Expires August 31, 1985	191
(November 1983) (Formerly 9-331) DEPARTMENT OF THE 4NTEERIOR version 10	5. LEASE DESIGNATION AND SERIAL NO.	•,
	NM-19842-''A''	
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.		
1. CFP 00 '87 Use "APPLICATION FOR PERMIT- TOP SUCE Droposals.)	7. UNIT AGREEMENT NAME	
2. NAME ODPGATOR	8. FARM OR LEASE NAME	
Pastland Oil Company	Federal "A"	
3. ADDREAS OF OPERATOR P.O.Drawer 3488, Midland, Texas 79702	1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface	Herradura Bend (Cherry	Can-
	11. SHC., T., E., M., OR BLK. AND BURVEY OR ARMA	yon)
1650' FSL and 1730' FEL		
14. PERMIT NO. 15. ELEVATIONS (Show whether DP, RT, GR, etc.)	Sec 28, T-22-S, R-28-E 12. COUNTY OB PABISH 13. STATE	NMPM
3062' GL - 3071' KB	Eddy NM	
	· · · · · · · · · · · · · · · · · · ·	
18. Check Appropriate Box To Indicate Nature of Notice, Report, or C		
NOTICE TO NOTIVIENTION TO : BUBBEQU		
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CANING	
REPAIR WELL CHANGE PLANS (Other)		
(Other) (Notr: Report results Completion or Recompletion	of multiple completion on Well etion Report and Log form.)	
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)* On May 19, 1987 set 4¹/₂" CIBP @ 3650' w/35'cement on top PB' Perforated zone 2595'-2599' w/2 shots per ft, Treated w/25 	TD 3615'. 00 gals Gel	
water and 2300 lbs sand. After recovering load, well has water per day with no oil.	been producing 45-75 bbis	
Casing in well consists of: (a) 103/4" surface csg @ 352' cemented w/350 sx Class C c (b) 4-1/2" production string set @ 4085' cemented with 13 Circulated.		
 Plugging Procedure as follows: 1. Load hole with 9.6# mud thru 2" tubing 2. Plug @ 2600' with 25 sacks cement and tag(across Delawa 3. Plug @ 1600' with 25 sacks cement 4. Plug @ 500' with 25 sacks cement and tag 5. Plug @ surface with 10 sacks 6. Set 4'X4' marker, cut off anchor and clean location. 	me Perfs) and	
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Production Superintenden	t7-31-87	
Travis Reed		
(This space for Federal or State office use)	c .1 07	
APPROVED BY TITLE	DATE <u>9-4-87</u>	
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side