

DAILY REPOET

DINERO OPERATING COMPANY
HUBER STATE #1

Taps No. 215

RECEIVED BY

JUL -3 1986

O. C. D.
ARTESIA, OFFICE

6/9/86

Move in and rig up Monument Rig 52. Rig up at 1 pm. Trip out of the hole with rods. Trip out of the hole with tubing. Rig up Bell and set CIBP at 5990 feet. Trip into the hole with tubing. SI.
RT9

6/10/86

Circulate hole and mix mud. Spot 7 sacks of C cement on top of plug. Pull to 3650 feet. Spot 25 sacks of C cement. Pull to 2550 feet. Spot 25 sacks of C cement. Pull to 2050 feet. Spot 35 sacks of C cement. Trip out of the hole. Perforate 4 shots at 450 feet. Trip into the hole with packer. Squeeze 35 sacks of C cement from 350. Trip out and set 10 sacks at surface. Rig down and move off.
RT 10