

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

**E.G.L. Resources, Incorporated**

3a. Address

**PO Box 10886, Midland, TX 79702**

3b. Phone No. (include area code)

**915-687-6560**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**FEL**  
**2,050' FSL & 1,490' FWL, Section 14, Township 24-S, Range 24-E**

Lease Serial No.

**NM 29202**

If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

**Baldrige Federal Com. No. 1**

9. API Well No.

**30-015-23970**

10. Field and Pool, or Exploratory Area

**Mosley Canyon Strawn**

11. County or Parish, State

**Eddy County, New Mexico**

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water Shut-Off

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☒ Recomplete

☐ Other

☐ Change Plans

☐ Plug and Abandon

☐ Temporarily Abandon

☐ Convert to Injection

☒ Plug Back

☐ Water Disposal

☐ Final Abandonment Notice

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. MIRU workover unit on 2-28-2000. Pressure test csg to 500 psig. Bled to zero in 40 seconds.

2. RU wireline unit. Set 1.71" CIBP in Otis pkr @ 10,810'. Bleed gas off well. Pressure test tbg & CIBP to 2,500 psig.

3. ND wellhead, release on-off tool, NU BOP. POOH w/ 2-3/8" tubing & On-Off tool skirt.

4. RIH w/ 4-1/2" RBP & pkr. Set RBP @ 10,060'. PUH w/ pkr tstg csg to 1,000 psi. Isolate csg leak to 5,580' to 5,644'.

5. Spot sand on RBP @ 10,060'. POOH w/ pkr. RIH w/ CIGR & set @ 5,328'. Establish injection rate into csg leak.

6. Cement squeeze csg leak w/ 200 sxs Class "C" neat cmt. Wait on cement.

7. Drill out cmt & CIGR from 5,309' to 5,633'. Pressure test csg to 500 psig. Held good.

8. Circulate sand off RBP @ 10,060'. Circulate well w/ 5% KCl wtr. Retrieve RBP & POOH w/ same.

9. RU wireline unit. Perforate Strawn formation from 9,824' - 38' (28 holes). RD wireline unit.

10. RIH w/ pkr, on-off tool, & 2-3/8" tbg. Set pkr @ 9,752'. Rise on-off tool. Circulate pkr fluid. Latch on-off tool.

11. ND BOP. NU wellhead.

12. Swab well in to flowing completion. Place well on production 12:10 pm March 10, 2000.

13. RD workover unit. Move off location.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

**John A. Langhoff**

Title **Petroleum Engineer**

Signature

Date **April 10, 2000**

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office