

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C15F
Dp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 20 '89

O. C. D.

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 1C2122S27E
7. Lease Name or Unit Agreement Name NICHOLS
8. Well No. 1
9. Pool name or Wildcat CARLSBAD WOLFCAMP EAST
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3311' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
GRAHAM ROYALTY, LTD

3. Address of Operator
5429 LBJ FREEWAY, STE 550 DALLAS, TX 75240

4. Well Location
Unit Letter C : 990 Feet From The NORTH Line and 2270 Feet From The WEST Line

Section 21 Township 22S Range 27E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3311' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU Baber Plugging Service. POH w/tbg & pkr. GIH w/2 3/8" tbg to 10,030'. Spot 25 sx cmt plug. GIH w/5 1/2" CIBP on WL. Hung @ 9300'. Set @ 9290'. Approved by NMOCC. GIH w/2 3/8" tbg to 9290'. Load hole w/10 ppg mud laden fluid. M&P 50 sx cmt from 9290'-8858'. POH w/2 3/8" tbg to 6406'. M&P 25 sx from 6406'-6188'. POH. Cut 5 1/2" csg @ 5507'. POH w/5 1/2" csg. GIH w/2 3/8" tbg to 5557'. M&P 100 sx cmt from 5557'-5295'. WOC 2 hrs. Tag top of cmt @ 5292'. M&P 25 sx cmt from 2000'-1900'. M&P 25 sx cmt from 1177'-1077'. M&P 40 sx cmt plug from 451'-351'. Cut off csg head. Spot 10 sx surface plug. Weld on steel plate. Erect dry hole marker.

Post ID-2
4-28-89
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>JACK D. BLEDSOE</u>	TITLE <u>PROD. SUPT.</u>	DATE <u>4/19/89</u>
TYPE OR PRINT NAME <u>JACK D. BLEDSOE</u>	TELEPHONE NO. <u>915/686-8646</u>	

(This space for State Use)

APPROVED BY <u>J.R. - DH</u>	TITLE	DATE
CONDITIONS OF APPROVAL ANY:		

1-11-90