

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

RECEIVED BY	
FEB 08 1984	
O. C. D. ARTESIA, OFFICE	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
Read & Stevens, Inc. ☒

3. Address of Operator  
P.O. Box 1518, Roswell, NM 88201

4. Location of Well

UNIT LETTER I 1980 FEET FROM THE South LINE AND 900 FEET FROM THE East LINE. SECTION 24 TOWNSHIP 23S RANGE 27E NMPM

5. Elevation (Show whether DF, RT, GR, etc.)  
3087.4' GR

XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

7. Unit Agreement Name

8. Farm or Lease Name

Cass Draw

9. Well No.

1

10. Field and Pool, or Wildcat

Und. North Loving Morrow

XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

12. County

Eddy

XXXXXXXXXXXXXXXXXXXX

XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☒ Connected to pipeline

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-1-84 Pull bridge plug. Clean up well. TP 2400psi.

2-2-84 Turned into line @ 10:20am 2-1-84. RP 3500psi, 1" Drifline, 2" Meter Run, 100"X1000psi meter, 800psi line pressure, 1.45 MMCF.

2-3-84 TP 800psi, 360 MCF, 33 BLW. Flowed to air, unloaded water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Stobly

TITLE Drilling & Production Manager

DATE 2-3-84

Original Signed By

APPROVED BY

TITLE

Leslie A. Clements

Supervisor District II

DATE FEB 10 1984

CONDITIONS OF APPROVAL, IF ANY: