

LIGHTFOOT "COM" NO. 1
1780' FSL, 2460' FEL
Sec. 14, T-24-S, R-28-E
Eddy County, New Mexico

Page 2

12. RIH w/tbg to 3150' & spot 75 sxs.
13. Tag plug. If tag good POH to 2700' & spot 75 sxs. POH & WOC 4 hrs.
14. Tag plug. If tag good POH to 675' and spot 75 sxs. POH & WOC 4 hrs.
15. Tag plug. If tag good POH & cutoff wellhead.
16. RIH w/2 jts tbg & spot 15 sxs @ surface.
17. Place a dry hole marker.
18. Location will be clean & all junk removed.
Plug procedure as per Mike Williams NMOCD Artesia.