

AUG 15 1984 9/5F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Hillin Production Co.

3. ADDRESS OF OPERATOR
P.O. Box 152, Odessa, Texas 79760

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
Unit P, 660' FSL & 660' FEL

14. PERMIT NO.
Letter dated 8-24-83

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GR - 3351.9'

RECEIVED BY
MAY 27 1985
O. C. D.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
NM 13984

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Cities "5" Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Byrnes Tank

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 5, Unit P, T-23-S, R-26-E

12. COUNTY OR PARISH
Eddy

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

P & A well as follows:

1. C.I.T.B.P. + 4850' + 35' cement

- 100' cement plug @ 5 1/2" casing cut off between 3700-3800'. 50' inside 5 1/2" and 50' outside in 7 7/8" open hole. Wait 4 hours and tag plug.
- 100' cement plug @ 1633' @ base of 9 5/8" casing. 50' inside and 50' in 11" open hole.
- 100' cement plug inside 9 5/8" casing @ 423' (base of 13 3/8" surface casing). wait 4 hours and tag plug. 423' is center of plug.
- 50' or 25 sx. (whichever covers more area) @ surface.

The above program was verbally approved by Mr. Bob Pitschke, per telephone conversation 8-6-84 w/John Boxell. Abandonment will commence week of 8-13-84.

1-17-85

Subject well was P & A as of this date using the above outlined procedure and tags were witnessed by BLM representative from Carlsbad. Mr. Bert Jones was notified of this plugging on 1-16-85.

18. I hereby certify that the foregoing is true and correct

SIGNED John D. Boxell

TITLE Production Engineer

DATE 8-7-84

(This space for Federal or State office use)

APPROVED BY Charles A. Scheller
CONDITIONS OF APPROVAL, IF ANY:

TITLE

AREA MANAGER
CARLSBAD RESOURCE AREA

DATE 8/12/84

5-24-85

Post ID-2
2-22-85
P&A