

RECEIVED BY

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

MAY 6 1985

DRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. O. C. D.

OIL
ARTESIA, OFFICE

OTHER Dry

No. 011
Drawer 10

Artesia, NM 88210

2. NAME OF OPERATOR

Exxon Corporation

3. ADDRESS OF OPERATOR

P. O. Box 1600, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1780' FSL and 1980' FEL of Section

14. PERMIT NO.

30-015-24577

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2992' GR

5. LEASE DESIGNATION AND SERIAL NO.

NM-19848

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

--

7. UNIT AGREEMENT NAME

--

8. FARM OR LEASE NAME

Blakemore Estate Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28 - 23S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandoned as follows:

CIBP at 6470' top w/ 35' cmt.

CIBP at 5480' top w/ 35' cmt.

Perf 5-1/2" w/ 2 shots at 660'.

Set plug at 4424-4524' w/ 20 sx cmt.


Set plug at 2894-2994' w/ 20 sx cmt.

Circ. 200 sx down 5-1/2" up to surface through perfs at 660'.

Cut off wellhead and installed dry hole marker.

P & A 12-31-83.

Post ID-2
5-10-85
P+R



18. I hereby certify that the foregoing is true and correct

SIGNED

Melba Knippling

TITLE Unit Head

DATE 4-30-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

5-2-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side