

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

DEC 19 1983

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. L-654

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Farm or Lease Name New Mexico DI State
3. Address of Operator P. O. Box 1600, Midland, Texas 79702	9. Well No. 3
4. Location of Well UNIT LETTER <u>Lot 3</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>23S</u> RANGE <u>26E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat-Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3476' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Set Casing</u> ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-26-83 Spud 12 12" hole @ 2400 hrs.
11-28-83 Set cmt plug @ 341' w/200 sx Cl C. TOC @ 310'
Set cmt. plug @ 248' w/200 sx Cl C. TOC @ 288'
Drld out to 660'.
11-29-83 Set cmt plug @ 558' w/200 sx Cl C.
Set cmt plug @ w/200 sx Cl C.
Set cmt. plug @ 615' w/200 sx Cl C.
Drilled out.
12- 3-83 Set 36 jts 8'5/8" 24# K55 csg @ 1434' w/DV tool at 668'. Cement 1st stage
w/650 sx BJ Lite and 400 sx Cl C. Pump wnd stage w/550 sx BJ Lite and 100
sx Cl C. Not returns. Temp. survey showed no cement above DV tool.
12- 3-83 Pump cement as follows @ 680'.
to 100 sx Cl C
12-10-83 50 sx Cl C
50 sx Cl C
50 sx Cl C
150 sx Cl C
200 sx Cl C
pea gravel RIH to 840'.
(OVER)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Edgar Runkel TITLE Unit Head DATE 15 December 1983
Original Signed By
Leslie A. Clements
APPROVED BY _____ TITLE Supervisor District II DATE DEC 19 1983

200 sx C1 C
pea gravel
200 sx C1 C
pea gravel
200 sx C1 C
20 sx C1 C
pea gravel
300 sx C1 C
pea gravel
300 sx C1 C
pea gravel
300 sx C1 C
pea gravel
300 sx CL C
ea gravel and frac. sand
300 sx C1 C
Run in hole 820'
200 sx C1 H
400 sx C1 C
200 sx C1 H
10 yds pea gravel, 10 yds sand
200 sx C1 H
6 yds pea gravel, 10 yds sand
200 sx C1 H
650 sx C1 C
TIH to 540'
160 sx C1 C
9 yds readi-mix; tag TOC @ 774'
18 yds readi-mix; tag TOC @ 378'
RIH to 317'
220 sx CL C;
circ 20 sx to surface.

Visitors on location during cementing

W. D. Weaver
Claude Tabor
Mike Williams
Mike Stubblefield
B. W. Weaver
Jim Wright
Tom Weheahus