

CHARLES S. READ  
PRESIDENT

NORMAN L. STEVENS, JR.  
VICE-PRESIDENT

*Read & Stevens, Inc.*

*Oil Producers*

*P. O. Box 1518*

*Roswell, New Mexico 88201*

November 11, 1983

Husky Oil Company  
6060 S. Willow Drive  
Englewood, CO 80111

Re: Non-Standard Location  
#1 Otis "34"  
1828.5' FNL & 1980' FWL  
Sec. 34-22S-27E  
Eddy Co., NM

Dear Sirs:

Read and Stevens, Inc. has proposed the drilling of the #1 Otis "34", on the W/2 portion unit at a non-standard location, located 1828.5' FNL and 1980' FWL of Sec. 34-22S-27E. As per Oil Conservation Division Rule 104 all offsetting operators must be notified of the unorthodox location. If no objections are entered within twenty days the application will be approved.

If I can answer any questions concerning this location, please call.

Sincerely,

READ & STEVENS, INC.

*Bruce Stubbs*

Bruce Stubbs

Drilling & Production Manager

BS:tb