CHARLES S. READ

NORMAN L. STEVENS, JR. VICE-PRESIDENT

、

Read & Stevens, Inc. Oil Producers P. O. Box 1518 Rossell, New Maxico 88201 November 11, 1983

Uriah Exploration 1604.W. Front St. Midland, TX 79701

> Re: Non-Standard Location #1 Otis "34" 1828.5' FNL & 1980' FWL Sec. 34-225-27E Eddy Co., NM

Dear Sirs:

Read and Stevens, Inc. has proposed the drilling of the #1 Otis "34", on the W/2 portion unit at a non-standard location, located 1828.5' FNL and 1980' FWL of Sec.34-22S-27E. As per Oil Conservation Division Rule 104 all offsetting operators must be notified of the unorthodox location. If no objections are entered within twenty days the application will be approved.

If I can answer any questions concerning this location, please call.

Sincerely, READ & STEVENS, INC.

nuce Stable

Bruce Stubbs Drilling & Production Manager

BS:tb

يبي بالمروابة فيعموهموناه