

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FEB 15 1993

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. D.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Union Oil Company of California

3. Address and Telephone No.

P. O. Box 671 - Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 1980' FWL - Sec. 1, T-23-S, R-31-E

5. Lease Designation and Serial No.

NM 22080

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Barclay Federal #1

9. API Well No.

30-015-24954

10. Field and Pool, or Exploratory Area

N. Sand Dunes Morrow

11. County or Parish, State

Eddy County, N. Mex.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Add perms in Morrow
(Middle Morrow)

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROCEDURE

1. ALL PROD. TREE VALVES SHOULD BE CHECKED FOR EFFECTIVE PRESSURE CONTAINMENT. THE EQUIPMENT SHOULD BE PROPERLY RATED AND CAPABLE OF HOLDING THE SHUT-IN TUBING PRESSURE. ANY DEFECTIVE EQUIPMENT SHOULD BE REPAIRED DURING THE COURSE OF THIS WORKOVER.
2. SHUT WELL IN.
3. RU SCHLUMBERGER PROD. LOGGING SERV. INSTALL & TEST 10,000 PSI LUBRICATOR & GREASE INJ W/ TYPE B. RIH W/GAUGE RING OR NO-GO ON SLICKLINE AND TAG PBTD TO INSURE PERF GUNS WILL GO THRU 1.875" PROFILE NIPPLE IN PKR.
4. RIH & PERF MORROW W/4 JSPF USING 1-11/16" THRU-TUBING PHASED ENERJET GUNS (W/8 GR CHGS) @ THE FOLLOWING INTERVALS: 14,600'-616' (55 SHOTS), 14,633'-636' (13 SHOTS), 14,642'-652' (41 SHOTS) - TOTAL 119 SHOTS.
5. POH W/WIRELINE AND RD SCHLUMBERGER.
6. FLOW WELL TO PRODUCTION FACILITIES AND PERFORM POTENTIAL TEST.

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass

Title Drilling Clerk

Date 2-2-93

(This space for Federal or State office use)

Approved by (ORIG. SGD.) DAVID R. GLASS

Title Drilling Clerk

Date 2-10-93

Conditions of approval, if any: