		t t	District No. 17 April 2015
orm 3160-5 UN ED STATES	SUBMIT IN TRI	:ATE*	Budget Bureau No. 1004-0135 Expires August 31, 1985
November 1983) Formerly 9–331) DEPARTMEN OF THE IN	TERIOR (Other Instruction verse side)	32 re- 5	LEASE DESIGNATION AND SERIAL NO.
BUREAU OF LAND MANAGE			NM-22619
			. IF INDIAN, ALLOTTEE OR TEIBE NAME
SUNDRY NOTICES AND REPO  (Do not use this form for proposals to drill or to deepen use "APPLICATION FOR PERMIT—" (	r plug fack to a diderent reservoi	1	
	such proposals.)		
OIL GAS	JAN 17 1985	7	UNIT AGREEMENT NAME
WELL WELL OTHER DRY			. FARM OR LEASE NAME
Exxon Corporation	Q. C. D.		Ross Federal
3. ADDRESS OF OPERATOR	ARTESIA, OFFICE	Li	. WELL NO.
P. O. Box 1600, Midland, TX 79702		' l	1
i. LOCATION OF WELL (Report location clearly and in accordance w	ith any State requirements.	<u>_</u>	O. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface			Wildcat-
:		1	1. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
2255' FWL and 2268' FSL			25 m22a n2/n
			25 - T23S - R24E  2. COUNTY OR PARISH   18. STATE
14. PERNIT NO. 15. ELEVATIONS (Show what 3853 GR	ether DF, RT, GE, etc.)	i	Eddy NM
			Eddy   Intr
6. Check Appropriate Box To India	cate Nature of Notice, Repo	ort, or Oth	er Data
NOTICE OF INTENTION TO:	1	SUBSEQUEN	T REPORT OF:
TEST WATER SHUT-OFF . PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING WELL
PRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATME	NT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON®	SHOOTING OR ACIDIS	ZING	ABANDONMENT <sup>®</sup>
REPAIR WELL CHANGE PLANS	(Other)		
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfament to this work.)	(Nore: Report Completion or pertinent details, and give pertinence locations and measured and trible continues are continued and trible continues and measured and trible continues are continued and trible continues are continu	Recompletion of dates, in	multiple completion on Well on Report and Log form.) cluding estimated date of starting any iepths for all markers and sones perti-
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfs	(Norm: Report Completion or Completion or Pertinent details, and give pertine the locations and measured and truth this well:  c. Tested. ce of oil. d as follows:	Recompletion of dates, in	on Report and Log form.) cluding estimated date of starting any
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfament to this work.)*  The following work was done in testing  Perf 4166 - 4182. Acdz. Tested.  CIBP @ 4130, cap w/ 35' cmt.  Perf 3934 - 4036. Acdz. Tested. Frace  Perf 3790 - 3894. Frac. Tested. Trace  This well will be plugged and abandoned  3750' CIBP; cap w/ 35' cmt.  2100' 35 sx C1C Neat  700' Perf 5-1/2" csg.  Pump 220 sx C1C Neat; 9 sx to pit	(Norm: Report Completion or Completion or Pertinent details, and give pertine the locations and measured and tribute this well:  Tested. See of oil.  d as follows:	Recompletion of dates, in	on Report and Log form.) cluding estimated date of starting any
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfament to this work.)*  The following work was done in testing  Perf 4166 - 4182. Acdz. Tested.  CIBP @ 4130, cap w/ 35' cmt.  Perf 3934 - 4036. Acdz. Tested. Frace  Perf 3790 - 3894. Frac. Tested. Trace  This well will be plugged and abandoned  3750' CIBP; cap w/ 35' cmt.  2100' 35 sx C1C Neat  700' Perf 5-1/2" csg.  Pump 220 sx C1C Neat; 9 sx to pit	(Norm: Report Completion or Completion or Pertinent details, and give pertine the locations and measured and tribute this well:  Tested. See of oil.  d as follows:	Recompletion of dates, in	on Report and Log form.) cluding estimated date of starting any iepths for all markers and sones perti-
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfament to this work.)*  The following work was done in testing  Perf 4166 - 4182. Acdz. Tested.  CIBP @ 4130, cap w/ 35' cmt.  Perf 3934 - 4036. Acdz. Tested. Frace  Perf 3790 - 3894. Frac. Tested. Trace  This well will be plugged and abandoned  3750' CIBP; cap w/ 35' cmt.  2100' 35 sx C1C Neat  700' Perf 5-1/2" csg.  Pump 220 sx C1C Neat; 9 sx to pit	(Norm: Report Completion or Completion or Pertinent details, and give pertine the locations and measured and tribute this well:  Tested. See of oil.  d as follows:	Recompletion of dates, in	on Report and Log form.) cluding estimated date of starting any iepths for all markers and sones perti-

## \*See Instructions on Reverse Side