

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
USE GAS	☒
LAND OFFICE	☒
OPERATION	☒

OIL CONSERVED BY DIVISION
P. O. BOX 2088
SANTA FE, N.M. 87501
NOV 26 1984
O. C. D.
ARTESIA, OFFICE

30-015-25031 API

Form C-103
Revised 10-1-7

1a. Indicate Type of Lease
State ☐ Fee ☒
b. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO WELL OR TO SEVERAL OR PLUG BACK TO DIFFERENT RESERVOIR.
USE APPLICATION FOR NOTICE TO WELL OR FOR PLUG BACK FOR SUCH PROCEEDINGS.)

1. OIL ☐ GAS ☒ OTHER ☐	7. Unit Agreement No.
2. Name of Operator Santa Fe Energy Company	8. Name of Lease No. Lovelace
3. Address of Operator 500 W. Illinois, Midland, TX 79701	9. Well No. 1
4. Location of well UNIT LETTER L 1090 FEET FROM THE West LINE AND 1439 FEET FROM THE South LINE, SECTION 27 TOWNSHIP 22S RANGE 27E NMPM.	10. Field and Pool, or Vicinity Undes. S. Carlsbad Morro
11. Elevation (Show whether DF, RT, GR, etc.) 3115.3' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 9 5/8" 40# K55 ST&C @ 5547'. Set DV tool @ 1482'.

Cmt 1st Stage: 1375 sx Howco lite 8# salt, 1/4% flocele, mixed @ 12.7 ppg, followed by 250 sx C1 C 2% CFR-2 mixed @ 14.8 ppg. Plug down @ 10:00 AM. Open DV tool, circ 6 hrs - no cmt.

Cmt 2nd Stage: 600 sx Howco lite 1/4# flocele 2% CaCl₂, 12.7 ppg & 200 sx C1 C 2% CaCl₂ 14.8#/gal. Close DV tool, did not circulate cmt - WOC 6 hrs. Ran temp survey. TOC @ 470'. Pick up 461' of 1" pipe. Cmt w/125 sx C1 C 2% CaCl₂. Circ cmt. WOC 28 1/4 hrs. Test to 500 psi 30 min. Drill out DV tool - test csg to 1500 psi 30 min. Drill cmt float & shoe. Test to 750 psi 30 min.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Billie Hood TITLE Sr. Production Clerk DATE 11-19-84

Original Signed By
Leslie A. Clements
Supervisor District II

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

DATE NOV 26 1984