

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
MAY 15 1985
O. C. D.
ARTESIA OFFICE

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	7. Unit Agreement Name
1. Name of Operator Ray Westall			8. Farm or Lease Name Buckaroo
2. Address of Operator P.O. Box 4 Loco Hills, NM 88255			9. Well No. 1
3. Location of Well UNIT LETTER 0, 1710 FEET FROM THE East LINE AND 580 FEET FROM THE South LINE, SECTION 28 TOWNSHIP 23S RANGE 28E NMPM.			10. Field and Pool, or Wildcat S. Culebra Bluff - RS
15. Elevation (Show whether DF, RT, GR, etc.) 3059. GR			12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Spud, 8 5/8", T.D., 5 1/2", 13 3/8" <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-85 Spud 17 1/2" hole @ 7:30 P.M.

4-16-85 Ran 11 jts. 424.66', 13 3/4" 54.5# csg. Cemented @ 405' w/500 sxs Class "C" 2% CaCl. Plug down @ 2:45P.M. Circulated 110 sxs. WOC 18 hrs.

4-21-85 Ran 2320.90' 54 jts. 24# 8 5/8" csg. Cemented @ 2332' w/950 sxs Howco-Lite, 150 sxs Class "C", Circulated 80 sxs to pit. Plug down @ 11:00 P.M. WOC 18 hrs. Test BOP 800# for 30 min. O.K.

5-6-85 T.D. 8,000'

5-11-85 Ran 199 jts. 8021.07' 5 1/2" csg. 17# J-55 St & C. Set & cemented @ 8,000' w/1st 775 sxs 50/50 Poz "C" 3# salt, 3/10% Halad-4. 2nd 1250 sxs 50/50 Poz "C" 6# salt, 1/4# Flocele. Plug down @ 12:15 A.M. Jet pits, set slips. Hold pressure on casing. W.O.C.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Westall TITLE Operator DATE 5-14-85

APPROVED BY ORIGINAL SIGNED BY LARRY BROOKS TITLE GEOLOGIST - NMOCD DATE MAY 20 1985

CONDITIONS OF APPROVAL, IF ANY: