


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

OIL CONSERVATION DIVISION



Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Ray Westall
3. Address of Operator
P.O. Box 4 Loco Hills, New Mexico 88255
4. Location of Well
UNIT LETTER 0 1710 FEET FROM THE East LINE AND 580 FEET FROM
THE South LINE, SECTION 28 TOWNSHIP 23S RANGE 28E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
Buckaroo
9. Well No.
1
10. Field and Pool, or Without
Und. S. Culebra Bluff-BS
11. Elevation (Show whether DF, RT, GR, etc.)
3059. GL
12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER Perfs & Acidizing Treatment ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-85 Perforated: 6614-6482 (5 shots total)
Acidized: 1,500 gal. 20% SRA acid 77. CIB @ 6450 will send for C-103

6-28-85 Perforated: 5728-44, 5874-5904 (94 holes) Delaware Formation
6-29-85 Acidized: 4,500 gal. 15% SRA acid.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Westall TITLE Operator DATE 7-3-85

APPROVED BY ORIGINAL SIGNED BY LARRY BROOKS GEOLOGIST - NMOGD TITLE DATE JUL 9 1985
CONDITIONS OF APPROVAL, IF ANY:

