

Budget Bureau No. _____
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Pogo Producing Company ✓	8. FARM OR LEASE NAME Federal Neff
3. ADDRESS OF OPERATOR P. O. Box 10340, Midland, Texas 79702-7340	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FWL	10. FIELD AND POOL, OR WILDCAT Livingston Ridge - Delaware
11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Section 25 T-22-S, R-31-E	12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, RT OR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	DILL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRAC TURE TREAT	MULTIPLE COMPLETE	FRAC TURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	Other: <u>Plug back</u>	
Other:		*NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log forms.	

NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.

17. *Sketch and describe in completed format on following state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

10/13/89 Flow & swab back load - short 381 BLW

10/14/89 Flow & swab back load - short 190 BLW

10/16/89 Flow & swab back load - all load recovered last hour swab (16) bbls fluid w/25%
oil cut & good gas show

10/17/89 Unseat pkr - P00H - GIH w/TAc - RU to pump w/86 rod string - short 280 BLW

[illegible][illegible]

10/20/89 Move in RU pump jack & prime mover

10/21/89 " " " " " " "

10/22/89 Start pumping 2:00 PM MDT - produced 227 BLW - short 53 BLW

10/23/89 Produced 9 B0, 53 BLW, 211 BSW - install production equipment

10/24/89 Produced 50 BO, 181 BW - install production equipment

10/25/89 Produced 101 B0, 50 BW - install production equipment

10/26/89 Produced 0 B0, 156 BW - 12 hrs - engine threw belts - hooking up battery

10/27/89 Produced 16 hrs - 129 B0, 63 BW - hooking up battery (continued)

18. I hereby certify ~~that the foregoing is true and correct~~

SIGNED Richard Wright TITLE Dist. Dirg. & Prod. Supt. DATE October 31, 1989

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

***See Instructions on Reverse Side**

SJS