

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0453201

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Squaw Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Undes. Sheep Draw Morrow Gas

11. SEC., T., R., M., OR BLK. AND
SUBSET OF AREA

Sec. 1, T23S, R25E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Exxon Corporation Attn: David A. Murray

3. ADDRESS OF OPERATOR
P. O. Box 1600, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

RECEIVED BY

AUG 7 1987

O. C. D.
ARTESIA, OFFICE

2479' FSL and 1880' FWL of Sec.

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GR 3695'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Spill Report

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-9-87 A valve on a service company's blender was left open allowing approximately 5-10 bbl of diesel to leak onto the location. The leak was stopped by closing the valve. The affected area covered most of the SW/4 of the location as well as an area 8' wide tapering to 6" wide, 200' in length, West of the location. The leak did not affect any surface water. The area was cleaned up by covering it with fresh dirt.

Danny Cortez and Shannon Shaw with the BLM were notified of this incident.

RECEIVED

JUL 16 10 45 AM '87

CARLSBAD RESOURCE
AREA HEADQUARTERS

ACCEPTED FOR RECORD

JUL 31 1987

SJS

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

for David A. Murray

TITLE Permits Supervisor

DATE 7-15-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side