

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-25484

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Marathon Oil Company

3. Address of Operator
P.O. Box 552, Midland, TX 79702

7. Lease Name or Unit Agreement Name
Delta Fee "C"

8. Well No.
1

9. Pool name or Wildcat
Und. E. Carlsbad (Wolfcamp)

4. Well Location
Unit Letter C : 1980 Feet From The West Line and 990 Feet From The North Line
Section 12 Township 22-S Range 27-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3093.3 GL 3109 KB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon Oil Co is proposing to add perfs, stimulate and install artificial lift in this well as per the procedure summarized below.
MIRU PU. Install BOP. POOH with Tbg. Test BOP. Perforate Wolfcamp with 2 JSPF 9849-54, 9829-36, 9816-20, 9436-41. Using PPI tool acidize perfs with 100 gallons per foot 15 % HCL. Swab back load. Pooh with stimulation tools. Install production tubing. ND BOP. NU Tree. Install pump and rods. RDMO PU. Set Pumping Unit. Hang well off and put on test.

RECEIVED

APR 28 1995

OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas M. Price TITLE AET DATE 4/27/95

TYPE OR PRINT NAME Thomas M. Price

TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY T. M. PRICE TITLE DISTRICT II SUPERVISOR DATE MAY 1 1995