

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S
LAND OFFICE
OPERATOR

OIL CONSERVATION DIVISION
RECEIVED BY POST OFFICE BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

APR 1 1986

O. C. D.

ARTESIA, CALIF.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

XXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

7. Unit Agreement Name

8. Farm or Lease Name
Cass Draw

9. Well No.
2

10. Field and Pool, or Wildcat
Wildcat Delaware

XXXXXXXXXXXXXXXXXXXXXXXXXXXX

12. County
Eddy
XXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXX

SUNDAY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)

1. OIL WELL ☐ GAS WELL ☐ OTHER Dryhole

2. Name of Operator
Read & Stevens, Inc.

3. Address of Operator
Post Office Box 1518, Roswell, New Mexico 88202

4. Location of Well
UNIT LETTER I . 890 FEET FROM THE East LINE AND 1980 FEET FROM
THE South LINE. SECTION 24 TOWNSHIP 23S RANGE 27E NMPM

5. Elevation(Show whether DF,RT,GR,etc.)
3100.7' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-28-86 RU MBW, LD rds & pmp, TOH w/tbg, PU 4 1/2" bit, TIH to 2410', TOH, PU Watson 5 1/2" CIBP, setting tool 5.60', TIH, set CIBP @ 2400', spot 40' cmt on top of plug: 2360'-2400', circ hole w/9.5#/gal Brine, 36 vis, TOH w/62jts 2 7/8", spot 25sx Class "C" cmt: 465'-215', LD 3jts, dropped 12jts, setting tool 384.27', top of fsh @ 1975.73', bott of fsh @ 2360', set 10sx plug: surf-30', cut off, inst dry-hole marker.

3-29-86 Clean loc, remove anchors, build dike around loc. Will notify when loc ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. C. Stubbs TITLE Drilling and Production Manager DATE March 31, 1986

APPROVED BY Danell Moore TITLE Geologist DATE 7/15/86

CONDITIONS OF APPROVAL, IF ANY:

Post 7D-2
4-11-86
YKA

