

- 7-2-97 REMOVE & REPLACE WELLHEAD ASSY. NUBOPE. R 6-3/4" BIT. TST 7-5/8"
DRILL FAIR CMT 5197-5425. CIRC. AND TST. RU WIRELINE. PERF 7-5/8" CSG.
4" GUN F/8290-8081, 1 SPF, 27 SHOTS
- 7-3-97 PKR 8290'. SPOT 250 GAL 15% HCl ; PUMP 250 GAL 15% ACID. PMP 2500 GAL 15%
W/Frac BALLS AND SPOT AT PKR. LOWER PKR 8314'. LD WORK TUBING.
- 7-8-97 RU & GIH W/3-1/2 TBG
- 7-9-97 RIH W/3-1/2 TBG TO 8010'. RU FRAC VALVE. FRAC 8081-8290 W/ 60,000 GAL VIKING
I-30; 122,000 #SD
- 7-15-97 RDPU