

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dist
Dpt

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-25758

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
K-3271

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well: RECEIVED
OIL WELL GAS WELL OTHER

James A

2. Name of Operator
Phillips Petroleum Co. ✓

8. Well No.
3

3. Address of Operator
4001 Penbrook St., Odessa, Texas 79762
O. C. D. S&A OFFICE

9. Pool name or Wildcat
Cabin Lake (Delaware)

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 2 Township 22-S Range 30-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3178.6' DF; 3167.6' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>Isolated Cherry Canyon Zone</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-29-92: MI & RU DD Unit. Pull out of hole rods & Pump. COOH with 2-7/8 tubing. Set RBP at 5750' pulled up at set RTTS pkr. TD 1000 PSI. Release RTTS pkr. COOH. GIH with Lok-Set pkr and prod assy on tubing. Pkr & S/N at 5570'. Land tubing. Remove BOP & run prod pump string.
5-14-92: Bbl oil - 2.8, bbl water - 184.6, Gas MCF - 6.8.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv. Regulation & Proration DATE 5-19-92

TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS DATE MAY 25 1992

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: