Form HEELES (Novambel 1883) (Formerly 9-331	BUREAU OF LAND MANAGEMENT Drawer DD		
SEP 08	SUNDRY NOTICES AND REPORTS ON WELLS  this form for proposals to drill or to deepen or plug back to a different reservoir.	NM 45236 6. IF INDIAN, ALLOTTEE OR TE	IBE NAME
OIARTESIA, O	AS OTHER	7. UNIT AGREEMENT NAME	
Santa Fe 3. ADDRESS OF OP	Energy Operating Partners, L.P.	8. FARM OR LEASE NAME  Triple S 33 Federal  9. WBLL NO.	
500 W. II  4. LOCATION OF W See also space At surface	linois, Suite 500, Midland, TX 79701 LLL (Report location clearly and in accordance with any State requirements.*	1 10. FIELD AND POOL, OR WILDCAT WILDCAT Bone Spring	
1980' FNI	& 2310' FEL	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	33, T-23S, R-31E 12. COUNTY OR PARISH 13. 8	FATE
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Ot		<u>M</u>
	NOTICE OF INTENTION TO	INER DOIG	
nent to this v	MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS  CHANGE PLANS  (Other)  (Note: Report results of Completion or Recompleted or Recomp	depths for all markers and zo	rting any nes perti-
7-24-87	to fish.  Drill from 2811-2883'. Cmt plug from 2850' to 2500' w. Resume drilling.	/300 sx. WOC 24 h	rs.
7-30-87	Run 8 5/8" csg. 104 jts, 32#, K55 LT&C csg & set @ 418 C lite poz, 4% D26, 7#/sk D44, 0.5% D112, 0.2% D46, tag Neat. Cmt did not circulate. Ran 1" pipe to 110'. Pt Circ 50 sx to surface. BLM witnessed. WOC 21 1/2 hrs manifold to 3000.	il in $w/200 \text{ sx Cl}$	C at
8-15-87	7 Ran 5 1/2" @ 9665' - 245 jts 17.0# N80 LT&C. DV tool @ 6615'. Cmt w/550 sx 50/50 C1 H poz w/2% D20, 5% D44, 5% D112, tail in w/200 sx C1 H, 0.5% D60, 0.2% D13. Cmt 2nd stage w/365 sx C1 C w/0.5% D60.		
8-16-87	Released rig 7:00 a.m.  ACCEPTED FOR RECORD  SJS  AUG 2 6 1987	AUG 21 1 1 CARLSEAT & AREA SEADQ	RECEIVED
8. I hereby certify	CARLSBAD, NEW MEXICO	12 PX	VED
signed <u>B</u> ,	illie Hard Sr. Production Clerk	DATE	
APPROVED BY	TITLE	DATE	

## \*See Instructions on Reverse Side