

Sterling Silver 32 No. 1

15 sx plug @ 4,080' to 4,034'
35 sx plug @ 698' to 589'
Cut off wellhead @ 5' below ground level
Set 50' cmt plug @ surface
Cap wellhead - weld on P&A marker

SANTA FE ENERGY OPERATING PARTNERS, L.P.