

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 13 '89

O. C. D.

WELL API NO. 30-015-25866
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NMLG8478
7. Lease Name or Unit Agreement Name Sterling Silver 32
8. Well No. 1
9. Pool name or Wildcat Undes. West Sand Dunes Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY Hole	
2. Name of Operator SANTA FE ENERGY OPERATING PARTNERS, L. P.	
3. Address of Operator 500 WEST ILLINOIS, SUITE 500, MIDLAND, TEXAS 79701	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 32 Township 23S Range 31E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) KB 3395'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A Well

11-17-88 Set CIBP @ 14,015'. Displace hole w/10# BW mud w/25# salt gel/BBL
thru Set plugs:
11-29-88 25 sx cmt plug @ 14,010' to 13,616'
25 sx cmt plug @ 13,225' to 12,831'
50 sx cmt plug @ 11,928' to 11,454'
25 sx cmt plug @ 9,040' to 8,880'
25 sx cmt plug @ 6,922' to 6,757'
Cut off csg @ 6183', pull 156 jts 7" csg.
35 sx cmt plug @ 6,225' to 6,150'. Witnessed by OCD
35 sx cmt plug @ 4,103'
Set 9 5/8" CIBP @ 4,080'.

Post ID-2
1-20-89
P&A

(See Attachment)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billie Hood TITLE SR. PRODUCTION CLERK DATE _____
TYPE OR PRINT NAME BILLIE HOOD TELEPHONE NO. 915 687-355

(This space for State Use)

APPROVED BY Danell Moore TITLE Geologist DATE 1/23/89

CONDITIONS OF APPROVAL, IF ANY: