

+
clsf
dp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088, Santa Fe, New Mexico 87504-2088
AUG - 5 1992

O. C. D.
MINING OFFICE

WELL API NO. 30-015-25886
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3589
7. Lease Name or Unit Agreement Name Pauline ALB State
8. Well No. 6
9. Pool name or Wildcat Wildcat Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RE-ENTRY
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 32 Township 23S Range 31E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3370.5' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
7-28-92. RUPU. Cut off 9-5/8" casing and welded on wellhead. Pick up 8-1/2" bit, crossover sub, 1 drill collar. RU power swivel and drilled cement plug #1 from 5' to 75'. Drilled cement plug #2 from 634-730'. Drilled cement plug #3 and CIBP 4060-4093'. Washed and reamed old hole to 4249'. Drilled from 4219-4223'. Tested BOP and casing at 3183' to 1500 psi for 15 minutes, OK. Washed and drilled 4223-4234'. Drill from 4234-4239'. Washed from 4239-5100'. Continue washing with shoe from 4722-5841'. Washed and reamed from 5841-6175'. Tagged top of 7" casing stub at 6175'. Washed and reamed 6188-6814'. Drilled cement and junk 6814-6819'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-4-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II
APPROVED BY _____ TITLE _____ DATE AUG 10 1992
CONDITIONS OF APPROVAL, IF ANY: