

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-100831

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Bat ARO Federal #1

9. API Well No.

30-015-25874

10. Field and Pool, or Exploratory Area

Undesignated

11. County or Parish, State

Eddy Co., NM

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2210' FNL & 660' FWL of Section 34-T23S-R24E (Unit E, SWNW)

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Acidize & swab

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-7-98 - Flow tested. Shut well in.

12-8-98 - Flowed well down. Swab & flow test. Released packer. TOOH with tubing and packer. Shut well in.

12-9-98 - Bled well down. TIH with 4-3/4" bit, drill collars and tubing. Took 325 bbls to break circulation. Drilled down 2'. TOOH with tubing, collars and bit. TIH with 4-3/4" shoe, drill collars and tubing. Tagged up at 8507'. Made 3' with shoe to 8510'. Shoe plugging off. TOOH with shoe - shoe was split and flared out. TIH with 4-3/4" bit, drill collars and tubing. Tagged up at 8508'. Drilled 2' to 8510'.

12-10-98 - Continue drilling. TOOH with tubing, drill collars and bit. TIH with 4-3/4" shoe with diamonds and wires, drill collars and tubing. Tagged up at 8510'. Made 1' in 3 hours. TOOH. TIH with lead block on sand line and tagged fish. TOOH with lead block. TIH with 4-5/8" short catch overshot with 3-1/16" grapple. Latched onto fish. Picked up 20000# over string weight. Set hydraulic jars off. Picked up and turned pipe to right to release RBP. TOOH with tubing, collars, jars and overshot. Had Baker Lokset packer in overshot. TIH with bit, scraper and tubing. Tagged PBD at 8900'. Circulated well clean with 2% KCL. TOOH with bit and scraper.

12-11-98 - TIH with RBP, packer and tubing. Set RBP at 8825'. Moved up and set packer at 8650'. Swabbed - zones communicated. Released packer. Moved packer up hole to 8533'.

14. I hereby certify that the foregoing is true and correct

CONTINUED ON NEXT PAGE:

Signed [Signature]
(This space for Federal or State office use)

Title Operations Technician

Date Jan. 5, 1999

Approved by _____
Conditions of approval, if any:

Title _____

Date _____

